

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

TP INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP ALLIANZ
Policy No:		Date of Loss:	24/05/2023
Vehicle Reg. No.:	SNF307T	Driveable?	
Party At Fault:	UNKNOWN	Driver (Insured):	WANG JINLIANG
Driver (TP):	NOOR IRSYAD BIN NOOR AZLEE		
Make/Model:	TOYOTA ALPHARD, 2.5 HYBRID SR C	Vehicle Reg. Date:	26/04/2022
Vehicle Colour:	CVT (A)		
Engine No:	WHITE	Chassis No:	AYH300140994
Odometer:	2AR2755568		
	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

*Not Notified
Repair B & paint
5-7 days*

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	3,208.70
Labour	40.00
Paintwork Labour	2,310.00
Towing	0.00
	40.00
Gross Total (S\$)	5,598.70
+ GST 8.00% (S\$)	447.90
Nett Amount (S\$)	6,046.60

This claim is handled by: JUNE PHUA LIAN HUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 May 2023)
 Parts: M1-MPV TOYOTA ALPHARD 2.5 HYBRID SR C CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNF307T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

SNF307T
 TP/AM/2022
 Dof: 24/5/23

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR BUMPER	CM	0.00	*290.00 F
2	1		*1 PC REAR BUMPER RH SIDE RETAINER RH	br	0.00	*65.00 F
3	1		*1 PC REAR BUMPER TOW COVER - SQUARE	mr	0.00	*35.00 F
4	1		*1 PC REAR BUMPER REVERSE SENSOR RH		0.00	*180.00 F
5	1		*6 PCS REAR BUMPER CLIP @2/PCE	Na	0.00	*12.00 F
6	1		*1 PC REAR BUMPER SIDE PAD RH	Bu	0.00	*130.00 F
7	1		*1 PC TAILGATE	Bu	0.00	*730.00 F
8	1		*1 PC TAILGATE INNER LOCK		0.00	*310.00 F
9	1		*1 PC TAILGATE INNER RUBBER	dist	0.00	*190.00 F
10	1		*1 PC TAILGATE EMBLEM - ALPHARD	Na	0.00	*55.00 F
11	1		*1 PC TAILGATE EMBLEM - HYBRID	Na	0.00	*45.00 F
12	1		*1 PC TAILGATE EMBLEM - E-FOUR	Na	0.00	*45.00 F
13	1		*1 PC REAR WINDSCREEN MOULDING	Na	0.00	*80.00 F
14	1		*1 PC REAR END PANEL OUTER		0.00	*350.00 F
15	1		*1 PC REAR END PANEL INNER TOP GARNISH	Bu	0.00	*105.00 F
16	1		*1 PC REAR TOOL BOX		0.00	*230.00 F
17	1		*1 PC SMART KEY SENSOR		0.00	*65.00 F

F=Franchise part.

Sub Total (\$\$) 2,917.00
 + Margin on L,N Items 10.00% (\$\$) 291.70
 Total Parts (\$\$) 3,208.70

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

1 1 1 ROLL REAR WINDSCREEN GUM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged-by Repairer

Signature:

Date:

Amount
 40.00
 Sub Total (\$\$) 40.00

Estimates on Labour

No Particulars

Labour Items

1 1) TO PANEL BEATING
 2 2) TO REMOVE AND REFIX REAR WINDSCREEN GLASS
 3 3) TO REMOVE AND REFIX SEAT, CARPAT, GARNISH ETC
 4 4) TO PUTTY AND RESPRAY ON REAR END PANEL, REAR FLOOR BOARD PANEL, TAILGATE, REAR BUMPER, REAR RH SIDE PANEL
 5 5) TO REMOVE AND REFIX REVSEER CAMERA, SMART KEY, SENSOR AND RESET SYSTEMY
 6 6) TO RUSTPROOFING

Lab.Type Amount
 New 1,000.00
 New 100.00
 New 100.00
 New 1,000.00
 New 50.00
 New 60.00

Gross Labour Cost (\$\$) 2,310.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >