

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: HL Assurance Pte Ltd
11 Keppel Road
#11-01 ABI Plaza
Singapore 089057

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Romeo Jonnalyn Alaam

Date: 29 May 2023

Preliminary Advice

Vehicle No	: SLK9017T	Accident Date	: 24/05/2023
Make	: TOYOTA COROLLA ALTIS	Policy No.	: MP311870
Assignment Date	: 25/05/2023	Excess	: S\$0.00
Date of Inspection	: 26/05/2023	Est. Duration of Repair	: 12
Inspection At	: BORNEO MOTORS (S) PTE LTD (UBI) 17 UBI ROAD 4 SINGAPORE 408611		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,787.44
Revised Amount	:S\$	22,615.54
Check Items (Estimated)	:S\$	6,573.50
Total	:S\$	29,189.04
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	31,769.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,231.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.