

MS Car Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875

Tel: 6385-1838 / 9725 4442 Fax: 6386-1838 Email: motorstopoffice@gmail.com / motorstopservices@gmail.com / msgroupoffice@gmail.com

TP Lin
Hui Rong

SJE : _____

Vehicle Nos : SMT1082Y

Date of Survey : _____

Model : Toyota Harrier

Contacts : _____

Year : _____

**** AGREED COR and Days with SJE ****

Amount : _____

Nos.	PARTS	QTY	UNIT S\$	Total S\$	REMARKS IF ANY
1	Tailgate <i>Dented</i>	1	\$ 2,379.00	\$ 2,379.00	✓ 1488
2	Tailgate windscreen molding set	1	\$ 150.00	\$ 150.00	✓
3	Tailgate logo emblem <i>new</i>	1	\$ 60.00	\$ 60.00	✓
4	Tailgate harrier emblem <i>new</i>	1	\$ 74.00	\$ 74.00	✓
5	Tailgate garnish <i>new</i>	1	\$ 1,300.00	\$ 1,300.00	✓
6	Tailgate hinge Lh	1	\$ 135.00	\$ 135.00	✓
7	Tailgate hinge Rh	1	\$ 135.00	\$ 135.00	✓
8	Tailgate auto damper Lh	1	\$ 1,155.00	\$ 1,155.00	✓
9	Tailgate auto damper Rh	1	\$ 1,155.00	\$ 1,155.00	✓
10	Tailgate inner handle	1	\$ 55.00	\$ 55.00	✓
11	Tailgate inner board	1	\$ 578.00	\$ 578.00	✓
12	Tailgate lock with cover	1	\$ 974.00	\$ 974.00	✓ 566
13	Tailgate weather strip <i>new cut</i>	1	\$ 442.00	\$ 442.00	✓ 395
14	Rear bumper <i>Dented</i>	1	\$ 1,415.00	\$ 1,415.00	✓ 395
15	Rear bumper diffuser <i>Dented</i>	1	\$ 455.00	\$ 455.00	✓
16	Rear bumper reflector Lh	1	\$ 60.00	\$ 60.00	✓
17	Rear bumper reflector Rh	1	\$ 60.00	\$ 60.00	✓
18	Rear bumper retainer Lh	1	\$ 84.00	\$ 84.00	✓
19	Rear bumper retainer Rh	1	\$ 84.00	\$ 84.00	✓
20	Rear bumper shield Lh	1	\$ 60.00	\$ 60.00	✓
21	Rear bumper shield Rh	1	\$ 60.00	\$ 60.00	✓
22	Rear bumper sponge <i>crackd.</i>	1	\$ 125.00	\$ 125.00	✓
23	End panel <i>Dented</i>	1	\$ 796.00	\$ 796.00	✓
24	End panel top cover <i>Dented</i>	1	\$ 445.00	\$ 445.00	✓ 361
25	End panel tailgate antenna sensor <i>end</i>	1	\$ 165.00	\$ 165.00	✓
26	Well panel	1	\$ 825.00	\$ 825.00	✓
27	Well panel top board	1	\$ 885.00	\$ 885.00	✓
28	Well panel tools tray Lh	1	\$ 175.00	\$ 175.00	✓
29	Well panel tools tray Rh	1	\$ 175.00	\$ 175.00	✓
30	Well panel sponge Lh	1	\$ 339.00	\$ 339.00	✓
31	Well panel sponge Rh	1	\$ 339.00	\$ 339.00	✓
32	Rear chassis frame Lh	1	\$ 2,177.00	\$ 2,177.00	✓
33	Rear chassis frame Rh	1	\$ 2,177.00	\$ 2,177.00	✓
34	Exhaust silencer box	1	\$ 667.00	\$ 667.00	✓
35	Exhaust mounting	3	\$ 38.00	\$ 114.00	✓
	<i>Reverse Sensor (2)</i> 265	530			
			Total Price	\$ 20,274.00	
			Less 25%	\$ 5,068.50	
			Sub Total Price	\$ 15,205.50	

Nos.	PARTS	QTY	UNIT S\$	Total S\$	REMARKS IF ANY
1	Tailgate windscreen sealant <i>new</i>	1	\$ 100.00	\$ 100.00	✓ 60
2	Tailgate garnish clips set <i>new</i>	1	\$ 60.00	\$ 60.00	✓
3	Tailgate inner board clips set <i>new</i>	1	\$ 80.00	\$ 80.00	✓ 30
4	Rear no. plate set <i>new</i>	1	\$ 65.00	\$ 65.00	✓
5	Rear bumper clips set <i>new</i>	1	\$ 80.00	\$ 80.00	✓ 30
6	End panel sealant <i>new</i>	1	\$ 100.00	\$ 100.00	✓ 60
7	End panel top cover clips set <i>new</i>	1	\$ 60.00	\$ 60.00	✓ 20
8	Well panel sealant <i>new</i>	1	\$ 120.00	\$ 120.00	✓
9	Exhaust gasket <i>new</i>	1	\$ 65.00	\$ 65.00	✓

		Total	\$ 730.00

Nos.	Claims Details : Labour and Spray Painting	Total S\$	REMARKS IF ANY
1	Labour to panel beat/cut/weld affected panels, realign and refit/ replace necessary affected parts	\$ 1,600.00	800
2	To putty and spray paint on accident affected portion	\$ 1,200.00	800
3	To remove and transfer rear windscreen to new tailgate	\$ 180.00	120
4	To transfer components to new tailgate	\$ 120.00	60
5	To disconnect/reconnect and check for proper wiring and electrical function	\$ 100.00	30
6	To apply anti rust coating	\$ 120.00	60
7	To remove and reinstall rear compartment trims	\$ 100.00	60
8	To remove and replace exhaust system	\$ 250.00	X
9	To diagnostic reset fault code back to manufactory setting	\$ 450.00	X
10	To dismantle and replace rear bumper reverse sensor with distance test	\$ 100.00	50
11	To check water leakage test of accident portion	\$ 80.00	X.
	Total	\$ 4,300.00	1580

PARTS TOTAL \$ 15,935.50
LABOUR TOTAL \$ 4,300.00
OVERALL TOTAL \$ 20,235.50

NAME OF SURVEYOR :

REMARKS :

total 17503.50
L/s: 16 K
06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

61c.