

振明摩哆

CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our ref: EST062/23/CIS

Your ref: To be advised

22-May-23

MS First Capital Insurance Limited

36 Robinson Road
#16-01 City House
Singapore 068877

Attn: Motor Claims Department

Dear Sir / Mdm

Re: Estimated cost of repair to Toyota Hiace no: PC7283Z

Date of accident: 20-05-2023

Parts supply:

1 pc Bonnet	S\$	887.50
2 pcs Bonnet hinges @\$69.90		139.80
1 pc Bonnet emblem		61.80
1 pc Bonnet lock		89.50
2 pcs Headlamps @\$555.90		1,111.80
2 pcs Headlamp clips @\$10.00		20.00
1 pc Front grille base		488.40
1 pc Front grille - Top		289.50
1 pc Front grille - Lower		332.50
4 pcs Front grille clips @\$3.50		14.00
1 pc Front bumper reinforcement - Top		395.80
1 pc Front bumper reinforcement - Lower		443.20
2 pcs Front bumper brackets @\$188.50		377.00
1 pc Front bumper lower grille		138.50
2 pcs Front bumper side cover @\$40.46		80.92
1 pc Front bumper tow cover		36.90
2 pcs Front bumper retainers @\$139.00		278.00
8 pcs Front bumper clips @\$3.50		28.00
1 pc Front support panel		439.60
1 pc Radiator		1,581.90
1 pc Radiator spare tank		215.60
2 pcs Radiator fan blade @\$145.50		291.00
1 pc Radiator fan cowling - Big Rectangle		276.50
1 pc Radiator fan cowling - round @\$215.60		431.20
1 pc Aircon condenser		1,477.80
1 pc Wiper tank		165.80
		<hr/>
		10,092.52
Less 25%:		<hr/>
		(2,523.13)
		<hr/>
		7,569.39

振明摩哆

CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Re: Estimated cost of repair to Toyota Hiace no: PC7283Z

Date of accident: 20-05-2023

Parts supply:

Balance b/f: S\$ 7,569.39

S/Nett Items

1 pc Bonnet sticker - Certis CISCO (S/Nett)	120.00
1 pc Bonnet sticker - AUXILIARY POLICE (S/Nett)	120.00
1 pc Front no. plate (S/Nett)	35.00

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.	800.00
To respray affected part.	700.00
To remove & refit aircon and top up aircon gas	120.00
To check wirings.	30.00
	<u>S\$ 9,494.39</u>