

# 振明摩托 CHIN MENG MOTORS

Hui Roy

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883  
Tel: 6747-4810 Fax: 6745-5018  
cmmotors@singnet.com.sg

Our ref: EST062/23/CIS

Your ref: To be advised

22-May-23

## MS First Capital Insurance Limited

36 Robinson Road

#16-01 City House

Singapore 068877

### Attn: Motor Claims Department

Dear Sir / Mdm

### Re: Estimated cost of repair to Toyota Hiace no: PC7283Z

Date of accident: 20-05-2023

#### Parts supply:

1 pc Bonnet <i>Dehd</i>	SS	887.50	✓
2 pcs Bonnet hinges @\$69.90 <i>new</i>		139.80	+
1 pc Bonnet emblem <i>new</i>		61.80	✓
1 pc Bonnet lock <i>new</i>		89.50	✓
2 pcs Headlamps @\$555.90 <i>Exhd</i>		1,111.80	✓
2 pcs Headlamp clips @\$10.00 <i>new</i>		20.00	✓
1 pc Front grille base <i>new</i>		488.40	+
1 pc Front grille - Top <i>Dehd</i>		289.50	✓
1 pc Front grille - Lower <i>Dehd</i>		332.50	✓
4 pcs Front grille clips @\$3.50 <i>new</i>		14.00	✓
1 pc Front bumper reinforcement - Top <i>Bent</i>		395.80	✓
1 pc Front bumper reinforcement - Lower <i>Bent</i>		443.20	✓
2 pcs Front bumper brackets @\$188.50 <i>Exhd</i>		377.00	✓
1 pc Front bumper lower grille <i>Dehd</i>		138.50	✓
2 pcs Front bumper side cover @\$40.46 <i>new</i>		80.92	+
1 pc Front bumper tow cover <i>new</i>		36.90	+
2 pcs Front bumper retainers @\$139.00 <i>RA Brand</i>		<del>278.00</del> - 139	
8 pcs Front bumper clips @\$3.50 <i>new</i>		28.00	✓
1 pc Front support panel <i>new</i>		439.60	+
1 pc Radiator <i>Dehd</i>		1,581.90	✓
1 pc Radiator spare tank <i>Dehd new</i>		215.60	+
2 pcs Radiator fan blade @\$145.50 <i>new</i>		291.00	+
1 pc Radiator fan cowling - Big Rectangle <i>new</i>		276.50	+
1 pc Radiator fan cowling - round @\$215.60 <i>new</i>		431.20	+
1 pc Aircon condenser <i>Dehd</i>		1,477.80	✓
1 pc Wiper tank <i>Dehd</i>		165.80	✓
		<u>10,092.52</u>	
Less 25%:		<u>(2,523.13)</u>	
		7,569.39	

# 振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883  
Tel: 6747-4810 Fax: 6745-5018  
cmmotors@singnet.com.sg

## Re: Estimated cost of repair to Toyota Hiace no: PC7283Z

Date of accident: 20-05-2023

### Parts supply:

Balance b/f: S\$ 7,569.39

### S/Nett Items

1 pc Bonnet sticker - Certis CISCO (S/Nett)	120.00	✓
1 pc Bonnet sticker - AUXILIARY POLICE (S/Nett) <i>Free</i>	120.00	✓
1 pc Front no. plate (S/Nett) <i>Bent</i>	35.00	✓

### Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To respray affected part.

To remove & refit aircon and top up aircon gas

To check wirings.

<del>800.00</del> <i>600</i>
<del>700.00</del> <i>500</i>
120.00 <i>?</i>
30.00 <i>✓</i>
<u>S\$ 9,494.39</u>

*Admin Lij*  
*1/2 26/05/23*

*05 Days*  
*Not Antlaised.*

*Excess: To be advised*

*Resurveyed. Admin Lij*  
*05/06/23* *J.S.*