

UEN: 202308089
 27 Pasir Ris St 72 #04-16 Whitewater Singapore 518767
 Tel: +65 91057898 Email: bernardteo@techwerkzautomotive.com

TP SMART
 Hui Roy

GK33419722

Vehicle Number : SMP1941P
 Make/ Model : Honda Fit

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
TAILGATE <i>Distal</i>		1	1057.20 <i>958</i>	-20.00 %	845.76 ✓
TAILGATE HINGE LH <i>3 Men</i>		1	53.20 X	-20.00 %	42.56 +
TAILGATE HINGE RH		1	53.20 X	-20.00 %	42.56 +
TAILGATE OUTER GARNISH <i>could</i>		1	187.20 ✓	-20.00 %	149.76 ✓
TAILGATE LOGO <i>nr</i>		1	57.10 ✓	-20.00 %	45.68 ✓
TAILGATE EMBLEM - FIT <i>nr</i>		1	65.10 ✓	-20.00 %	52.08 ✓
TAILGATE DAMPER LH <i>3 pr</i>		1	104.20 X	-20.00 %	83.36 +
TAILGATE DAMPER RH <i>m</i>		1	104.20 ✓	-20.00 %	83.36 +
TAILGATE LOCK <i>Dmgd</i>		1	157.10 ✓	-20.00 %	125.68 ✓
TAILGATE LOCK CATCH <i>nr</i>		1	43.00 X	-20.00 %	34.40 +
TAILGATE WEATHSRSTRIP <i>ut</i>		1	109.50 ✓	-20.00 %	87.60 ✓
TAILGATE INNER TRIM BOARD <i>could</i>		1	305.70 ✓	-20.00 %	244.56 ✓
REAR WINDSCREEN MOULDING <i>nr</i>		1	152.60 ✓	-20.00 %	122.08 ✓
TAILGATE LAMP LH <i>3 pr ut</i>		1	275.30 ✓	-20.00 %	220.24 ✓
TAILGATE LAMP RH <i>3 pr nr could</i>		1	275.30 ✓	-20.00 %	220.24 ✓
TAILLAMP LH <i>3 pr could</i>		1	407.00 <i>358</i> ✓	-20.00 %	325.60 ✓
TAILLAMP RH <i>3 pr could</i>		1	407.00 <i>358</i> ✓	-20.00 %	325.60 ✓
REAR BUMPER <i>Distal</i>		1	635.90 <i>545</i> ✓	-20.00 %	508.72 ✓
REAR BUMPER CENTRE GARNISH <i>Reprinted.</i>		1	317.40 X	-20.00 %	253.92 +
REAR BUMPER SIDE GARNISH LH <i>Dmgd</i>		1	32.60 ✓	-20.00 %	26.08 ✓
REAR BUMPER SIDE GARNISH RH <i>could</i>		1	32.60 ✓	-20.00 %	26.08 ✓
REAR BUMPER CENTRE LOWER GARNISH <i>could</i>		1	169.40 ✓	-20.00 %	135.52 ✓
REAR BUMPER SIDE RETAINER LH <i>3 pr</i>		1	35.20 ✓	-20.00 %	28.16 ✓
REAR BUMPER SIDE RETAINER RH		1	35.20 ✓	-20.00 %	28.16 ✓
END PANEL TOP GARNISH <i>Distal</i>		1	106.40 ✓	-20.00 %	85.12 ✓
END PANEL <i>Distal</i>		1	474.10 ✓	-20.00 %	379.28 ✓
SPARE TYRE PANEL <i>Distal</i>		1	910.60 ✓	-20.00 %	728.48 ✓
SPARE TYRE PANEL TOP BOARD <i>Empled</i>		1	321.90 ✓	-20.00 %	257.52 ✓

252

REAR SPARE TYRE PANEL TOOLS COMPARTMENT SPONGE	<i>Cashed</i>	1	225.40	✓	-20.00 %	180.32	✓
REAR CHASSIS FRAME LH	<i>Revs</i>	1	849.20	X	-20.00 %	679.36	+
REAR BUZZER	<i>new</i>	1	74.50	✓	-20.00 %	59.60	✓
ANTENNA ASSEMBLY	<i>new</i>	1	133.20	X	-20.00 %	106.56	+
REAR TAILLAMP PANEL LH	<i>Buckled</i>	1	195.60	✓	-20.00 %	156.48	✓
REAR TAILLAMP PANEL RH	<i>Buckled</i>	1	195.60	✓	-20.00 %	156.48	✓
REAR FENDER LH	<i>} Buckled</i>	1	910.90	✓	-20.00 %	728.72	✓
REAR FENDER RH		1	910.90	✓	-20.00 %	728.72	✓
REAR FENDER INNER TRIM LH	<i>crushed</i>	1	299.90	✓	-20.00 %	239.92	✓
REAR FENDER INNER TRIM RH	<i>crushed</i>	1	299.90	✓	-20.00 %	239.92	✓
REAR FENDER COWLING LH	new <i>torn</i>	1	103.70	✓	-20.00 %	82.96	+
REAR FENDER COWLING RH	new <i>torn</i>	1	103.70	✓	-20.00 %	82.96	+
FUEL TANK COVER LH	<i>new</i>	1	69.20	X	-20.00 %	55.36	+
FUEL TANK COVER RIVET	<i>new</i>	4	8.60	X	-20.00 %	27.52	+
REAR EXHAUST PIPE	<i>Best</i>	1	758.40 <i>645</i>	✓	-20.00 %	606.72	✓
REAR EXHAUST MOUNTING	<i>new</i>	1	48.00	X	-20.00 %	38.40	+
REAR EXHAUST HEAT SHIELD	<i>crushed</i>	1	97.00	✓	-20.00 %	77.60	✓
BONNET	<i>Dented</i>	1	789.80	✓	-20.00 %	631.84	✓
BONNET SEAL	<i>cut</i>	1	28.00	✓	-20.00 %	22.40	✓
BONNET INSULATOR	<i>crushed</i>	1	121.00	✓	-20.00 %	96.80	✓
BONNET HINGE LH	<i>} Best</i>	1	52.00	✓	-20.00 %	41.60	✓
BONNET HINGE RH		1	52.00	✓	-20.00 %	41.60	✓
BONNET DAMPER	<i>new</i>	2	10.00	X	-20.00 %	16.00	+
BONNET LOCK	<i>Dented</i>	1	259.00 <i>98</i>	✓	-20.00 %	207.20	✓
BONNET LOCK CABLE	<i>new</i>	1	92.10	X	-20.00 %	73.68	+
BONNET STAND	<i>new</i>	1	35.00	X	-20.00 %	28.00	+
BONNET STAND HOLDER	<i>new</i>	1	8.00	X	-20.00 %	6.40	+
FRONT GRILLE COMPLETE ASSY	<i>Smashed</i>	1	844.00 <i>426</i>	✓	-20.00 %	675.20	✓
HEADLAMP LH	<i>} Crashed</i>	1	1125.00	✓	-20.00 %	900.00	✓
HEADLAMP RH		1	1125.00	✓	-20.00 %	900.00	✓
HEADLAMP BRACKET LH	<i>} Cashed</i>	1	65.00	✓	-20.00 %	52.00	✓
HEADLAMP BRACKET RH		1	65.00	✓	-20.00 %	52.00	✓
FRONT BUMPER	<i>Dented</i>	1	698.00 <i>568</i>	✓	-20.00 %	558.40	✓

FOCUS HAEDLAMP	RnR	80.00	0.00 %	80.00 ²⁰
RNR BOTH FRONT AND REAR SEAT	RnR	300.00	0.00 %	300.00 ¹²⁰
RNR REAR INTERIOR TRIMMING AND GARNISH	RnR	200.00	0.00 %	200.00 ¹⁰⁰
RNR INTERIOR ROOF LINING AND CARPET	RnR	350.00	0.00 %	350.00 ^x
RNR INTETIOR PILLAR, DOOR STEP TRIMING AND SEAT BELTS	RnR	350.00	0.00 %	350.00 ¹⁸⁰
LABOUR CHARGE (CENTER)	RnR	2000.00	0.00 %	2,000.00 ⁴⁰⁰
RNR AND CALOBRATE REAR VIEW CAMERA	RnR	180.00	0.00 %	180.00 ⁵⁰

4950

Repair

Description	Severity	Cost	Markup/Disc %	Price
B-PILLAR INNER PANEL LH	Medium			
B-PILLAR INNER PANEL RH	Medium			
FRONT CHASSIS MEMBER LH	Medium			
FRONT FENDER LH	Medium			
FRONT FENDER RH	Medium			
REAR CHASSIS FRAME RH	Medium			
REAR DOOR LH	Medium			
REAR DOOR RH	Medium			

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINT (REAR)	Full spray	2700.00	0.00 %	2,700.00 ¹⁶⁰⁰
SPRAY PAINT (FRONT)	Full spray	1200.00	0.00 %	1,200.00 ¹⁰⁰⁰
SPRAY PAINT (ROOF)	Full spray	1400.00	0.00 %	1,400.00 ⁷⁰⁰

3300

General Labor Subtotal	10,800.00
Paint Labor Subtotal	5,300.00
Labor Subtotal	16,100.00

Summary

Adrian Lj
h/s 29/05/23
21 Days

Repair Cost	39,067.12
Discount(0 %)	(0.00)
	39,067.12
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	39,067.12

Supplementary: 956.80
total: 25128
h/s: 20.1K

TECHWERKZ AUTOMOTIVE PTE LTD

UEN: 202308089K
 27 Pasir Ris St 72 #04-16 Whitewater Singapore 518767
 Tel.: +65 9105 7898 Email: bernardteo@techwerkzautomotive.com

Vehicle Number : SMP1941P

Parts		SUPPLEMENTARY			Model : Honda Fit	
Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum	
INTAKE MANIFOLD SENSOR	<i>New</i>	1	187.00	<i>X</i> -20.00 %	149.60	<i>X</i>
RADIATOR TOP HOSE	<i>Trusled</i>	1	85.00	<i>✓</i> -20.00 %	68.00	<i>✓</i>
RADIATOR BOTTOM HOSE	<i>new</i>	1	95.00	<i>X</i> -20.00 %	76.00	<i>X</i>
AIRCON DISCHARGE PIPE	<i>Best</i>	1	204.00	<i>✓</i> -20.00 %	163.20	<i>✓</i>
AIRCON SUCTION PIPE	<i>Best</i>	1	197.00	<i>✓</i> -20.00 %	157.60	<i>✓</i>
AIRCON RECEIVER PIPE	<i>Best</i>	1	233.00	<i>✓</i> -20.00 %	186.40	<i>✓</i>
AIRCON COMPRESSOR	<i>new</i>	1	865.00	<i>X</i> -20.00 %	692.00	<i>X</i>
FRONT BUMPER UNDER PANEL/COVER	<i>Dislited</i>	1	245.00	<i>✓</i> -20.00 %	196.00	<i>✓</i>
FRONT WHEELHOUSE EXT PANEL LH	<i>} Repair</i>	1	208.00	<i>X</i> -20.00 %	166.40	<i>X</i>
FRONT WHEELHOUSE EXT PANEL RH		1	208.00	<i>X</i> -20.00 %	166.40	<i>X</i>
HORN	<i>Repd</i>	1	82.00	<i>✓</i> -20.00 %	65.60	<i>✓</i>

1046

Parts Subtotal 2,087.20

Labor

len 20% 836.80

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price	
RNR INTAKE MANIFOLD SENSOR	RnR	80.00	0.00 %	80.00	<i>X</i>
RESET & DIAGNOSTIC FUNCTION	RnR	120.00	0.00 %	120.00	<i>✓</i>

120

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To identify damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No additional claims allowed
- Supplementary: **Summary** is subject to final approval by Insurance Company

Adrian Lj
 31/05/23.

General Labor Subtotal 200.00

Paint Labor Subtotal 0.00

Labor Subtotal 200.00

Supplementary: 956.80

Repair Cost 2,287.20

Discount(0 %) (0.00)

2,287.20

Excess (0.00)

GST(0.00 %) 0.00