

106/101 wet
ASS REC. BY: John

REF:

CS/CT123005398/RVP3

911A

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLS 5209R
at Workshop m/s MOTOR IMAGE
of 25, LAM KEE RD
Insured: CTI
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record) _____
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 73K
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Turn Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SLS 5209R Yr Regn: 2017 186P
Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
☐ Truck / ☐ Trailer or
Make: SUBARU FORESTER 2.0I-LSR 1995
Colour: WHITE A/C: Insured / Std / NI / NA
Sp. Reading: 054528 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JF15J5K05J4098823
Gen. Cond: Good ☒ Fair ☐ Poor ☐ Burnt
Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or
Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or
Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or
Tyre Size: F: 225/65R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or WESTLAK

Front Rear
R/Bal. 7 mm R/Bal. 7 mm
L/Bal. 7 mm L/Bal. 7 mm
D.O.A. 24/05/23 D.O.I. 29/05/23
Survey held at MOTOR IMAGE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
0/2 FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 40K

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: _____

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

) S + RS, SI

) Photos

) Others

TOTAL

IMAGE ENTERPRISES PTE. LTD.
LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0144/2023
DATE : 25-MAY-2023

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#15-00 SPRINGLEAF TOWER
SINGAPORE S(079909)
TEL : 6389 6111
FAX : 6222 1033

OWNER'S NAME : LEE CHIEN YEE
ADDRESS : 717 BT TIMAH ROAD

S(269741)
TELEPHONE NO : 9677 4470

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : PNPV2022-00003376 FWD
VEHICLE NO : SLS5209R
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YB15000
CHASSIS NO : JF1SJ5KC5JG098823
MILEAGE : 1 KM
DATE IN : 25/05/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 25/05/2023

Print Date : 25/05/2023
Print Time : 19:02:29

ATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLS5209R

/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST CHINA TAIPING-CB6559U		
2 ZZ/001	DOA:24/MAY/2023 TIME:1635 HRS LOCATION:ALONG NAMLY AVENUE		
3 ZZ/002	REPLACE FRONT BUMPER, ENERGY ABSORBER, BUMPER BEAM, RH FENDER	3500.00	1200
4 ZZ/003	RESpray FRONT BUMPER, BUMPER BEAM AND RH FENDER	3000.00	1040
5 ZZ/004	TO CONDUCT FRONT LIGHTING TEST	50.00	
6 ZZ/005	225/65R17 TYRE 1 PC 702	400.00	?
7 ZZ/006	TRANSFER/BALANCE TYRE/RIM	28.00	
8 ZZ/007	4 WHEEL ALIGNMENT	200.00	
9 ZZ/008	DISMENTLE & REFIX UNDERCARRIAGE (FRT RH) TO FACILITATE REPAIR	300.00	?
10 ZZ/009	REMOVE & REFIX FRT HEADLAMP WASHER & PIPING	150.00	100
11 ZZ/011	SUNDRIES	100.00	20
12 ZZ/10	FAULT DIAGNOSTIC (RESET)	280.00	
	TOTAL LABOUR CHARGES	8008.00	

/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 SUPPORT CROMEN ,FRONT RIGHT ?	20107FJ021			12.00	
2 ARM ASSY F RH ? COUNTER MAESURE SG020	20202SG001			506.90	
3 PLATE ARM COMPL FRH ?	20216FJ021			33.30	
4 STRUT COMPL F RH ?	20310SG100			270.10	
5 STRUT MT F ?	20320FG012			74.00	
6 STABILIZER LK ?	20420XA000			85.10	
7 TYRE VALVE m/	23142GA040			8.50	
8 DISC WHEEL AL 17 ser/	28111SG130			1500.00	
9 HOUSING F RH ?	28313SC001			244.20	
10 DRV SFT ASSY F92 F92 ?	28321SG010			740.00	
11 HUB UNIT COMPL F ?	28373FL000			236.80	
12 GR BOX ASSY P/S EPS ?	34110SG050			2615.90	
13 FRT FENDER RH 4/	57120SG0209P			277.50	
14 BRKT CORNER F RH m/	57707SG000			37.00	
15 BRKT CORNER F LH X	57707SG010			37.00	
16 BRKT SD F LH X	57707SG030			13.00	
17 BUMPER FACE F NA (FOR H/L WSH) de/	57709SG030			610.50	
18 BACK BEAM CPL F 2/ X	57711SG0009P			296.00	
19 ENERGY ABSOR F X	57722SG020			129.50	
20 COVER HOOK F STD X	57731SG220			4.40	
21 MUD GUARD ASSY F RH de/	59110SG021			111.00	
22 LAMP ASSY HEAD EOF RH ?	84002SG220			2380.00	
23 LAMP ASSY-SIDE TURN MIRROR RH ser/	84401AJ000			102.00	
24 CLIP BMPR *16PCS m/	909140007			38.40	
25 CLIP *4PCS m/ (REAR MUD GUARD CLIP)	909140065			7.60	

J PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
26 R VIEW MIR UNIT RHR ?	91036SG844			488.40	
27 COVER MIR BODY RH X	91054AJ221			37.00	
28 FRONT NUMBER PLATE X	WM001			45.00	
SUB TOTAL		0.00	0.00	10941.10	0.00
LESS DISCOUNT ()		0.00	0.00	0.00	0.00
GRAND TOTAL		0.00	0.00	10941.10	0.00
OVERALL TOTAL		10941.10			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

ARY OF ESTIMATE FOR VEHICLE REGN NO SLS5209R

TOTAL LABOUR CHARGES	8008.00
TOTAL SPARE PARTS CHARGES	10941.10
GRAND TOTAL	18949.10 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

Repair - 4p 8000008
29/05/23 @ 1540

5 days

Resy 54 parts

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	991A
Vehicle No.:	SLS5209R
Vehicle to be Exported:	No
Intended Deregistration Date:	29 May 2023
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0I-L CVT AWD SR
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	FB20YB15000
Chassis No.:	JF15J5KC5JG098823
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,744.00
Original Registration Date:	27 Sep 2017
First Registration Date:	27 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$13,744.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Sep 2027
PARF Rebate Amount:	\$9,620.00
COE Expiry Date:	26 Sep 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,711.00
COE Rebate Amount:	\$23,243.00
Total Rebate Amount:	\$32,863.00

The information contained herein is correct as at 29 May 2023

OK

Subaru Forester 2.0i-L Sunroof

\$75,800 Instalment \$1,152/mth

Shortlist

Get Warranty

Loan Calculator



Overview Financial Photo Research

Depreciation	i \$15,690 / year
Reg. Date	24-Oct-2017 (4yrs 4mths 23days COE left)
Manufactured	i 2017
Mileage	66,000 km (11.8k / year)
Transmission	Auto
Engine Cap	1,995 cc
Road Tax	i \$1,208 / year
Power	110.0 kW (147 bhp) View specs of the Subaru Forester (2013-2019)
Curb Weight	i 1,591 kg
COE	i \$48,109
OMV	i \$13,383
ARF	i \$13,383
Dereg Value	i \$30,549 as of today

No. of Owners

