



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JQA 3386

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER ASSY	WARPED / DENTED	1,288.90	638.00
2	REAR BUMPER REFLECTOR	NOT NECESSARY	187.20	-
2	REAR BUMPER RETAINER	BENT / NECESSARY	172.80	172.80
2	REAR BUMPER BRACKET	NOT NECESSARY	177.40	-
1	REAR BUMPER REINFORCEMENT	BENT / WARPED	393.30	393.30
1	REAR BOOTLID ASSY	TO REPAIR SEE LABOUR	1,476.90	-
1	REAR LEFT TAILLAMP	REUSE	792.30	-
1	REAR RIGHT TAILLAMP	REUSE	792.30	-
1	REAR END LOWER PANEL	TO REPAIR SEE LABOUR	848.30	-
	LESS 25% DISCOUNT		-1,532.35	-301.03
			4,597.05	903.07
<b><u>SPECIAL NETT ITEMS</u></b>				
10	REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
4	REAR BUMPER REVERSE SENSOR (SN)	MALFUNCTION	1,000.00	200.00
1	REAR NO PLATE WITH GARNISH (SN)	NOT NECESSARY	100.00	-
			1,160.00	230.00
<b><u>LABOUR</u></b>				
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOTLID ASSY AND REAR END LOWER PANEL.		1,000.00	400.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION.		1,000.00	400.00
	TO CHECK REAR LIGHTING AND WIRING.		50.00	30.00
	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.		140.00	50.00
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA.		140.00	30.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR.		80.00	30.00
			2,410.00	940.00
<b>GRAND TOTAL</b>			<b>8,167.05</b>	<b>2,073.07</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,650.00</b>

Report Ref No. CS3/AGI21010775/Dqy3e2-1

**ANG BRYAN TANI**

**Automotive Assessor / Investigator**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.