



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref: CS3/AGI21010775/Dqy3e2-1

C/O TAN KOK QUAN PARTNERSHIP

Date: 16/06/2023

1 WALLICH STREET #07-02

GUOCO TOWER SINGAPORE 078881

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 5515E	Veh. Inspected	JQA 3386
Policy No.	CF.clm.1242.22-auto	Coverage (\$)	0.00
Claim No.	C10012020 /JM	Excess (\$)	0.00
Assign From	SAMANTHA CHEW	Assign Date	29/05/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CAMRY 2.0G (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	PN153BK5107009011	Colour	BLACK
Odometer	121270 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	FIRENZA	6 mm
L/H Front Tyre	215/60 R16	FIRENZA	6 mm
R/H Rear Tyre	215/60 R16	FIRENZA	6 mm
L/H Rear Tyre	215/60 R16	FIRENZA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/10/2021	Inspection Date	26/10/2021
Survey held at	ARC MOTORWORKS PTE LTD 10 KAKI BUKIT ROAD 2, #01-21, FIRST EAST CENTRE, SINGAPORE 417868		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-----------------------