

Not Authorised
Repair B&P point

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel Nc Fax No. : 62571330
CO./ GST Reg. No. 201019626G
SHC5687A

AAD2305-108

Vehicle No.:
Chassis No.:
Co UEN.:
Vehicle Make:
Vehicle Model:
Date of Accident:
Third Party Insurer:
Date of Registration:

29 MAY 2023

SHC5687A
JTDKB3FUX03096443
200303878K
TOYOTA
PRIUS GEN 4
25/2/2023
GBB3583E/ *Lampac*
30/12/2022

PART

LIST

1	COVER, FRONT BUMPER	\$	<i>SL</i>	659.40	X
1	HOOD SUB-ASSY	\$	<i>B</i>	1,243.20	✓
1	INSULATOR, HOOD	\$	<i>SL</i>	518.07	X
1	HINGE ASSY, HOOD, LH	\$	<i>n</i>	74.34	X
1	HINGE ASSY, HOOD, RH	\$	<i>n</i>	74.34	X
TOTAL		\$		2,569.35	
25%		\$		642.34	
		\$		1,927.01	

SPECIAL NETT

1	FRT BUMPER CLIP	\$	<i>nn</i>	65.00	X
1	BONNET INSULATOR CLIP	\$	<i>nn</i>	65.00	✓
TOTAL		\$		130.00	
TOTAL PARTS		\$		2,057.01	

LABOUR

To rust-proofing of the affected areas.	\$	600.00	<i>300</i>
Putty and spray painting of the affected portion.	\$	1,200.00	<i>2200</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	<i>1200</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00 X

Trans-cab Auto Services Pte Ltd

AAD2305-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHC5687A

To Transfer Of Fender Fittings, Attachments And Perform
Water Seepage Test.

	\$	<i>nn</i> 170.00 X
TOTAL	\$	<u>4,350.00</u>
OVERALL TOTAL	\$	<u><u>6,407.01</u></u>

2 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: