

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/05/2023
User ID : BoonChewTay

Section A - Accident Details

Registration Number	SHF233T
Case Reference Number	TAX/05/23/2080
Registration Date	14/12/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TAN KIANG CHIANG (CHEN JIANZHANG)
Type of Accident	Side Swipe
Accident Date and Time	26/5/2023 5:35 PM
Accident Reported Date and Time	27/5/2023 11:10 AM
Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118532
Special Instruction to ARC, if any	TP/RIGHT PORTION
Prepared Date and Time	27/5/2023 1:29 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$0.00
Total Spray Cost	\$1,952.00	\$0.00
Total Spare Part Cost	\$3,502.34	\$0.00
Total Other Cost	\$840.00	\$0.00
TOTAL COST	\$7,308.34	\$0.00
Temp Sum Total	\$7,300.00	\$0.00
Number of Repair Days	7.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	27/05/2023 1:41 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/05/2023

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O REPAIR RH PORTION	\$1,014.00	
Total Labour	\$1,014.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY FRONT DOOR RH	\$378.00	
O RESPRAY RH REAR DOOR	\$378.00	
O RESPRAY ROCKER PANEL MOULDING	\$220.00	
O RESPRAY CENTRE PILLAR RH	\$220.00	
O RESPRAY REAR FENDER RH	\$378.00	
O RESPRAY REAR BUMPER	\$378.00	
Total Spray Painting & Panel Beating	\$1,952.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O WASH AND VACUUM	\$60.00	
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00	
O APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	
O TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	
O TRANSFER DOOR MECHANISM	\$240.00	
O REPLACE SUNDRY PARTS	\$100.00	
Total Other Costs	\$840.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.17	Replace	na X
		6700147152	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,407.80	25.00	\$1,055.85	Replace	R X
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	na -
		7585047910	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$649.10	25.00	\$486.83	Replace	na X
		6700347210	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	R X
		6875020122	HINGE ASSY, REAR DOOR, UPPER RH	1.00	\$107.00	25.00	\$80.25	Replace	R X
		6877052031	HINGE ASSY, REAR DOOR, LOWER RH	1.00	\$93.90	25.00	\$70.43	Replace	R X
		6863047050	CHECK ASSY, REAR DOOR	1.00	\$199.40	25.00	\$149.55	Replace	R X
		8572047150	DOOR REAR MOTOR ASSY, POWER WINDOW REGULATOR, RH	1.00	\$996.60	10.00	\$896.94	Replace	R X
		6980347020	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	1.00	\$223.50	25.00	\$167.63	Replace	R X
		6160147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	25.00	\$707.33	Replace	R X
Total					\$6,561.00		\$5,085.26		X

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									