

Certification for Bus Repairs

CBR REF NO. : BB20226008

Depot : BB Report No.: AR-2022-3878 BUS VEHICLE NO. : SBS3843R
 Driver's Co no. & Name : 81629 Tan Lian Poh @Seck Lee Sian
 Accident Date : 30/11/2022

Date in : 01/12/2022

Date Out : 06/12/2022

Yr Of Reg	Make / Model	Chassis No.
2014	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P927EA168506

Stock Code	Description	Quantity	Total Material cost(S\$)
30750012	EXTERIOR RR O/S CORNER;F/GLASS	1	\$817.00
30541715	REAR REVERSE LAMP;B9TL EU5	1	\$81.00
99002081	PAINT C6000 VOLVO PURPLE	1	\$21.12
TOTAL FOR PARTS			SS 919.12
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	(3) Workshop Labour for Repair and Replace Bus Damage & Parts	SS	376.00
2	Contractor's repair charges	SS	-
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST			SS 376.00
Repair cost of Advertisement / Livery			SS -
TOTAL DAMAGE			SS 1295.12

Certification for Bus Repairs

CBR REF NO. : BB20226008



Depot :

BB

Report No.: AR-2022-3878

BUS VEHICLE NO. : SBS3843R

Driver's Co no. & Name : 81629 Tan Lian Poh @Seck Lee Sian

Accident Date : 30/11/2022

Date in : 01/12/2022

Date Out : 06/12/2022

Yr Of Reg	Make / Model	Chassis No.
2014	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P927EA168506
TOTAL DAMAGE		SS 1295.12
Overheads		SS 388.54
Towing Charges		SS -
Repair Period : 1 day(s)	Loss of Use	SS 421.31
TOTAL LOSS		SS 2104.97

Prepared By : Choo Wee Huat

Date : 11/12/2022

Approved By
Workshop Mgr : Thomas Tan Phue Koong

Date : 14/12/2022

	Survey Fee	refer to Group Claims
TOTAL DUE	SS	2104.97

Acknowledged
By Depot Safety : Lee Kok Leong

Date : 20/12/2022

* This is computer generated document and does not require signature