

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 2022-3413T/RC/AL Date: 10th July 2023

Our Ref: CS1/CNB23005414/Dpy3e2

M/s Central Narcotics Bureau (MHA09)

Corporate Services Division Blk B Police Cantonment Complex 393 New Bridge Road Singapore 088763 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SBS 3843R INSURED VEHICLE: SLL 9142J

ACCIDENT DATE: 30/11/2022

We thank you for your instruction on 14/04/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SBS 3843R from M/s Vicom Ltd.
- b) Singapore Accident Statement of Vehicles SBS 3843R.
- c) Police Report of Vehicles SLL 9142J
- d) Colour damaged vehicle photographs of SBS 3843R.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SBS 3843R

Make & Model : Volvo B9TL 9.4L Auto Turbo ABS

: 2014

Year of Registration Chassis Number Engine Capacity : YV3S4P927EA168506

Engine Capacity : 9364 cc



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

2.	Our finding is that the repair cost of \$1,295.12 (before GST) quoted by M/s Vicom Ltd is fair &	ķ
	reasonable.	

3. We recommend that the repairs of the entire damage require about <u>1 (One)</u> working days to complete.

Vehicle Inspected By:



ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.