

SBS Transit Ltd
205 BRADDELL ROAD
SINGAPORE 579701



VICOM LTD
385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555
Facsimile (65) 6458 1040

www.vicom.com.sg
Company Registration No: 198100320K

SURVEY REPORT

GENERAL INFORMATION			
VAC Ref. No.	: 571894	Claim No.	: AR-2022-3878
Accident Date	: 30/11/2022	Claim Type	: THIRD PARTY
Assignment Date	: 06/12/2022	Policy No.	:
Survey Date	: 06/12/2022	Finalised Dt.:	
Survey Report Date	: 27/12/2022	Insured Veh.:	: SLL9142J

VEHICLE PARTICULARS			
Vehicle No.	: SBS3843R	Chassis No.	: YV3S4P927EA168506
Registration Date	: 16/09/2014	Engine No.	: D9193127
Make	: VOLVO	Engine Cap.	: 9364 CC
Model	: B9TL 9.4L AUTO TURBO	Transmission	: AUTOMATIC
		Colour	: WHITE /PURPLE

CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)			
Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	: 552158.2		

<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE (mm)</u>
FRONT RH	275/70R22.5	PIRELLI	7
FRONT LH	275/70R22.5	PIRELLI	7
REAR RH	275/70R22.5	PIRELLI	7
REAR LH	275/70R22.5	PIRELLI	7

SURVEY CONDUCTED AT	
550 BUKIT BATOK ST.23 SINGAPORE 659519 TEL:66653767	

REMARKS	
[1]Workshop Estimate : S\$ 1,295.12	
[2]Our Adjustment : S\$ 1,295.12	
[3]Repair Period : 1 days	
[4]We have not authorised repairs. This survey was carried out on without prejudice basis:	

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	1	Exterior Rr O/S Corner F/Glass	Torn	817.00	817.00 ✓
2	1	Rear Reverse Lamp B9tl Eus	Cracked	81.00	81.00 ✓
3	1	Paint C6000 Volvo Purple	Necessary	21.12	21.12 ✓
Subtotal				: 919.12	919.12
TOTAL				: 919.12	919.12
TOTAL FOR SPARE PARTS				: 919.12	919.12

VICOM LTD**SURVEY REPORT****Annex B: Adjustment on Labour and Spray Painting**

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Workshop labour for repair and replace bus damage & parts	376.00	376.00 ✓
TOTAL FOR LABOUR AND SPRAY PAINTING		376.00	376.00

Summary

Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
TOTAL FOR SPARE PARTS	919.12	919.12
TOTAL FOR LABOUR AND SPRAY PAINTING	376.00	376.00
TOTAL REPAIR COST	1295.12	1295.12

VICOM LTD
SURVEY REPORT
Annex C: Conclusion

SBS3843R @ 30/11/2022

ASSESSOR'S REPORT

At the place of inspection, we saw this vehicle sustained rear right portion damage.

The damages seen during our survey were rear bumper corner rh, reverse lamp rh and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

We examined all the rear right portion damages and assessed they were from a collision or impact nature.

By cross-referencing with the e-filed report, we were satisfied the damages were consistent with the circumstances of accident as detailed.

ASSESSOR'S RECOMMENDATION

Sbs Transit Ltd - (Bukit Batok Bus Depot) estimated a repair cost of S\$1,295.12. We adjusted it to S\$1,295.12 on a part-by-part basis.


Accordingly, we recommend repairs to this vehicle be carried out on a part-by-part basis at S\$1,295.12.

The repairs would require a period of 1 working days.

We submit our survey report for your kind attention and would add the survey was carried out to the best of our ability, knowledge and experience.

REMARKS

SBS Transit, as owner of a large fleet and having an infrastructure of own workshops to maintain its buses at various depots, would have the parts price at costs. The parts are in the inventory. Correspondingly, the labour charge is actual cost based on man hours expended for the repairs. SBS Transit provides transportation to the general public. The repairs carried out by SBS Transit workshops is not a profit entity.



Favacho Patrick Gerard
for VICOM Ltd