

08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/HISB23005415/4993

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJN 89224

at Workshop m/s 24

of _____

Insured: SHB66002

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$ 70k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: 17483301

Veh No: SJN 89224 Yr Regn: 06/06/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Toyota harrier c.c 1986

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 126420 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 25U 600066111

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/45 R 20

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FAUKER

Front 6 mm Rear 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 27/05/23 D.O.I. 29/05/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & H.P.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction By 18.

NHT 036499
Lender 0144630

12/6/23 4/5 @ 24.00 informed Allen.

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$)

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

not Afford
29/05/23
1/5 \$24,000
7 days

VEHICLE No: SJN 8922U

1PC	REAR WINDSCREEN	17	\$1,455.20	X
1PC	REAR WINDSCREEN MOULDING	17	\$185.30	X
1PC	TAILGATE	2	\$2,499.10	X
1PC	TAILGATE 'HARRIER' EMBLEM	1er	\$105.00	✓
1PC	TAILGATE WEATHERSTRIP	17	\$399.20	X
1PC	TAILGATE INNER LOCK	17	\$498.20	X
2PCS	TAILGATE DAMPERS @\$366.10	17	\$732.20	X
1PC	TAILGATE INNER TRIM BOARD	17	\$681.80	X
1SET	TAILGATE INNER TRIM BOARD CLIPS	17	\$50.00	X
1PC	TAILGATE INNER PULL GARNISH	17	\$48.90	X
1PC	TAILGATE OUTER CHROME	17	\$752.30	X
1PC	REAR BUMPER	22	\$1,450.20	✓
2PCS	REAR BUMPER REFLECTORS @142.10	17	\$284.20	X
1PC	REAR BUMPER TOW COVER	17	\$60.00	X
1PC	REAR BUMPER SPONGE	17	\$335.20	✓
2PCS	REAR BUMPER SIDE RETAINERS @\$141.50	1er	\$283.00	✓
1PC	REAR END PANEL	3er	\$785.10	✓
1PC	REAR END PANEL TOP GARNISH	17	\$228.90	X
2PCS	TAILLAMPS @\$945.10	17	\$1,890.20	X
2PCS	TAILLAMP LOWER GARNISHS @\$645.10	17	\$1,290.20	X
2PCS	TAILLAMP PANELS @\$455.80	17	\$911.60	X
2PCS	REAR FENDERS @\$1299.30	17	\$2,598.60	X
2PCS	REAR FENDER LOWER SPLASH SHIELDS @\$153.10	17	\$306.20	X
1SET	REAR FENDER LOWER SPLASH SHIELD CLIPS	17	\$30.00	X
2PCS	REAR FENDER INNER TRIM BOARDS @\$781.10	17	\$1,562.20	X
1PC	REAR AIR VENT LH	17	\$143.80	X
1PC	REAR FLOOR PANEL TOP SPONGE CARPET	17	\$442.10	X
1PC	REAR FLOOR PANEL TOP BOARD LH	17	\$552.10	X
1PC	REAR FLOOR PANEL TOP BOARD RH	17	\$589.10	X
2PCS	REAR FLOOR PANEL TOP BOARD LOCKS @\$105.00	17	\$210.00	X
1PC	REAR FLOOR PANEL	2	\$1,148.20	X
1PC	REAR EXHAUST	17	\$662.10	X
1PC	REAR EXHAUST MOUNTING	17	\$50.80	X
1PC	REAR BATTERY BRACKET TRAY	17	\$335.10	X
1PC	BONNET	2er	\$2,655.10	✓
1PC	BONNET CHROME MOULDING	1er	\$345.00	✓
2PCS	BONNET HINGES @\$165.00	3er	\$330.00	✓
1PC	BONNET INSULATOR	17	\$288.90	X
1SET	BONNET INSULATOR CLIPS	1er	\$50.00	✓
1PC	BONNET RUBBER	17	\$65.00	X

866.11

185
65 x 2 = 130
715.50

1881.30

252

4607.91

*1PC	BONNET LOCK	Self		\$245.10	/
1PC	BONNET LOCK CABLE	17		\$188.90	X
1PC	FRONT BUMPER	Dij	904.20	\$1,350.10	/
2PCS	FRONT BUMPER SIDE RETAINERS @\$145.00	Self	904.20 = 160	\$290.00	/
1PC	FRONT BUMPER INNER RETAINER	Self		\$282.50	/
1PC	FRONT BUMPER LOWER GRILLE	Twl		\$225.10	/
1PC	FRONT BUMPER SPONGE CENTRE	70rn	340.10	\$356.90	/
2PCS	FRONT BUMPER SIDE SPONGES @\$145.00	70rn		\$290.00	/
1PC	FRONT BUMPER REINFORCEMENT	Self		\$645.20	X
2PCS	FRONT BUMPER REINFORCEMENT BRACKETS @\$165.00	nn		\$330.00	X
1PC	FRONT BUMPER UNDER COVER	17		\$345.90	/
1SET	FRONT BUMPER UNDER COVER CLIPS	17		\$50.00	X
1PC	FRONT GRILLE ASSY	One		\$1,455.00	/
1PC	FRONT GRILLE LOGO	17		\$105.00	/
2PCS	FRONT FOG LAMP GARNISHS @\$145.10	Twl		\$290.20	/
2PCS	FRONT FOG LAMPS @\$450.00	One		\$900.00	/
1PC	FRONT GRILLE OUTER CHROME	Self	640.10	\$850.10	/
1PC	HEADLAMP N/S	holder one	5201.22	\$7,108.10	/
1PC	HEADLAMP O/S	holder one	5201.22	\$7,108.10	/
2PCS	HEADLAMP LOWER BRACKETS @\$155.10	Self		\$310.20	/
2PCS	HEADLAMP TOP PANELS @\$425.10	Self		\$850.20	/
1PC	FRONT SUPPORT PANEL ASSY	Self		\$1,021.10	/
1PC	FRONT SUPPORT PANEL TOP GARNISH	17		X \$388.30	/
1SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS	17 X NN		\$45.00	X
2PCS	FRONT SUPPORT PANEL SIDE GARNISHS @\$211.80	de/70rn		\$423.60	/
2PCS	FRONT FENDERS @\$1415.00	Self	1448.50	\$2,830.00	/
2PCS	FRONT FENDER INNERSHIELDS @\$311.00	de/70rn		\$622.00	/
2PCS	FRONT FENDER 'HYBRID' EMBLEMS @\$150.00	NZ		\$300.00	X
1SET	FRONT FENDER INNER SHIELD CLIPS	17		\$50.00	/
1PC	FRONT FENDER INNER PANEL N/S	17		\$699.30	X
1PC	FRONT WHEEL HOUSING PANEL N/S	17		\$1,225.10	X
1PC	WIPER PANEL GARNISH	17		\$455.10	X
1SET	WIPER PANEL GARNISH CLIPS	17		\$45.00	X
1PC	FRONT BRACE PANEL	Self		\$121.00	/
1PC	FRONT DOOR N/S	17		\$1,745.10	X
1PC	AIR CLEANER BOX ASSY	17		\$1,025.10	X
1PC	AIR CLEANER BOX FILLTER	17		\$120.10	X
1PC	AIR CON SUCTION HOSE	17		\$344.50	X
1PC	AIR CON DISCHARGE HOSE	17		\$515.60	X
1PC	AIC CON LIQUID PIPE	17		\$188.90	X
1PC	AIR CON CONDENSER	Self/20rn		\$1,223.10	/
2PCS	AIR CON SIDE GARNISHS @145.00	Regul		\$290.00	X
1PC	RADIATOR	Self/20rn		\$1,961.80	/
1PC	RADIATOR FAN ASSY	One/70rn	1455.10	\$1,635.10	/
1PC	FUSE BOX COVER TOP	17		\$245.10	X
1PC	FUSE BOX COVER LOWER	17		\$311.10	X
1PC	HORN UNIT	17		\$90.00	X
1PC	FRONT AIR RESONATOR BOX	17		\$425.10	X
1PC	FRONT AIR DUCT	nn		\$185.00	X

(252/)

1PC	FRONT CENTRE CROSS MEMBER MOUNTING BRACKET	11	\$180.00	X
1PC	ENGINE MOUNTING N/S	11	\$350.00	X
1PC	ENGINE MOUNTING O/S	11	\$350.00	X
1PC	WASHER TANK	11	\$221.00	X
			\$70,498.80	
			LESS 25%	\$52,874.10

	S.NETT			
1SET	REAR BUMPER CLIPS	11	\$50.00	✓
1PC	REAR END PANEL SEALANT	11	\$50.00	40
1PC	REAR WINDSCREEN SEALANT	11	\$50.00	X
1PC	REAR WINDSCREEN INNER SEAL	11	\$50.00	X
1SET	REAR BUMPER REVERSE SENSOR	no function	\$280.00	200
1SET	REAR FLOOR PANEL INSULATOR	11	\$120.00	X
1PC	REAR FLOOR PANEL SEALANT	11	\$80.00	X
1SET	REAR FENDER INNER TRIM BOARD CLIPS	11	\$60.00	X
1SET	REAR BUMPER LOWER SPOILER	Dis	\$1,500.00	1,200.00
1PC	REAR LICENCE PLATE	11	\$50.00	X
1PC	FRONT LICENCE PLATE CHROME	Set	\$150.00	80
1SET	FRONT BUMPER CLIPS	11	\$50.00	✓
1BOL	RADIATOR COOLANT	11	\$50.00	20
1SET	FRONT LOWER SPOILER	Dis	\$1,500.00	1,200.00

TO CHECK WIRING	\$100.00	20
TO DISMANTLE & REFIX REAR WINDSCREEN	11 \$150.00	X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$150.00	80
TO DISMANTLE & REFIX TAILGATE MECHANISM	11 \$100.00	X
TO DISMANTLE & REFIX ENGINE FOR REPAIR CHASSIS	11 \$450.00	X
TO DISMANTLE & REPLACED REAR EXHAUST	11 \$60.00	X
TO CONDUCT WHEEL ALIGNMENT	11 \$120.00	X
TO SPRAY RUST PROOFING	\$200.00	80
TO RESET & DIAGNOSE.REPROGRAMME SYSTEM	\$380.00	100
TO REFILL AIR CON GAS	\$100.00	✓
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$4,500.00	1400
TO PUTTY & SPRAY PAINTING	\$2,800.00	1000
TOTAL	\$66,024.10	1800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-32/24.05
252
2409303
2440
3590
30123.03
20098