

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJY2207J

at Workshop m/s

of _____

Insured: SMJ3797M

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$70k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

419e

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

17A 23181

Veh No: SJY2207J Yr Regn: 12/08/10.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M /

Make: Mif Lencer GTX c.c 1584

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 137899 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMY5NCS3AAU000275

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/50R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 26/05/23

D.O.I. 29/5/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Fr.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20710k.

checked 11-08-2030 30 / 7yr 2nth
Bonnet fibre cracked already

12/6/23 have h14
2/5 \$14,000 insured Alan. (red \$8078, 562)

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 10

1) 12/6/23

: Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2)

Add Fee:

: Site Insp (\$

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

Report Format: TP

Lump Sum / I.B.I. (\$) 14000

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

TOTAL

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

Not followed
 29/5/23
 2/5 @ 14,000/
 alph. Ate up
 10 days
 NETT ITEM

VEHICLE No: SJY 2267J

| QTY | DESCRIPTION | PRICE | UNIT | PRICE |
|------|--|------------|----------------|------------|
| 1PC | REAR BUMPER | 727 | del/air | \$885.00 |
| 1PC | REAR BUMPER LOWER SPOILER | 728 | one | \$1,080.00 |
| 1PC | REAR BUMPER SIDE RETAINER O/S | | surf | \$45.00 |
| 1PC | REAR BUMPER BEAM | | su | \$234.00 |
| 1PC | REAR BUMPER TOP BEAM | | su | \$118.00 |
| 1PC | REAR BUMPER SPLASH SHIELD O/S | | 11 | \$116.00 |
| 1SET | REAR BUMPER SPLASH SHIELD CLIPS O/S | | 11 | \$30.00 |
| 1PC | REAR EXHAUST | | su | \$866.00 |
| 2PCS | REAR EXHAUST MOUNTINGS @\$20.00 | | u7 | \$40.00 |
| 1PC | REAR END PANEL | 482 | surf | \$484.00 |
| 1PC | REAR END PANEL TOP GARNISH | 168 | twi | \$203.00 |
| 1PC | REAR FENDER INNER TRIM O/S | | tom | \$282.00 |
| 1SET | REAR FENDER INNER TRIM CLIPS O/S | | 1er | \$40.00 |
| 1PC | BOOTLID | 726 | m/gerf | \$980.00 |
| 1PC | BOOTLID OUTER GARNISH | 197 | one | \$430.00 |
| 1PC | BOOTLID REAR LOGO | | 1er | \$39.00 |
| 1PC | BOOTLID 'LANCER' EMBLEM | | nf | \$42.00 |
| 1PC | BOOTLID C&C LOGO | | nz | \$45.00 |
| 1PC | BOOTLID WEATHERSTRIP | 168 | twi | \$199.00 |
| 2PCS | TAILLAMPS @520.00 | 505 | m/sun olscve | \$1,040.00 |
| 1PC | REAR FLOOR PANEL | | u | \$949.00 |
| 1PC | REAR FLOOR PANEL TOP BOARD | 282 | tom | \$316.00 |
| 1PC | FRONT BUMPER | 781 | 11 | \$1,045.00 |
| 1PC | FRONT BUMPER LOWER SPOILER | 780 | del/air | \$1,080.00 |
| 2PCS | FRONT BUMPER LOWER CENTRE GARNISHS @\$105.00 | | tom | \$210.00 |
| 2PCS | FRONT BUMPER SIDE RETAINERS @\$98.00 | 65x2=130 | surf | \$196.00 |
| 1PC | FRONT BUMPER LICENCE PLATE GARNISH | 101 | u | \$102.00 |
| 2PCS | FRONT BUMPER FOG LAMPS @\$650.00 | 625 | m/s tom olscve | \$1,300.00 |
| 1PC | FRONT BUMPER UNDER COVER | | 11 | \$248.00 |
| 1SET | FRONT BUMPER UNDER COVER CLIPS | | 11 | \$40.00 |
| 1PC | FRONT BUMPER FOG LAMP O/S | | 11 | \$295.00 |
| 1PC | FRONT BUMPER FOG LAMP GARNISH O/S | | 11 | \$105.00 |
| 1PC | FRONT BUMPER BEAM | 281 | surf | \$366.00 |
| 1SET | FRONT BUMPER CLIPS | | 1er | \$40.00 |
| 2PCS | HEADLAMPS @\$1280.00 | 691x2=1382 | holder one | \$2,560.00 |
| 1PC | FRONT SUPPORT PANEL | 545 | surf | \$816.00 |
| 2PCS | FRONT FENDERS @\$680.00 | 455x2=910 | surf/3uc | \$1,360.00 |
| 2PCS | FRONT FENDER INNER SHIELDS @\$190.00 | | m/s tom olscve | \$380.00 |
| 1PC | AIR DUCT | | twi | \$148.00 |
| 1PC | AIR CON CONDENSER | 820 | surf/air | \$1,018.00 |
| 1PC | AIR CON FAN ASSY | 480 | one/air | \$650.00 |

107
 820
 480

1PC RADIATOR
 1PC RADIATOR FAN ASSY
 2PCS RADIATOR TOP BRACKETS @\$50.00
 2PCS FRONT GRILLES @\$145.00
 1PC FRONT BRACE PANEL
 1PC BONNET LOCK
 2PCS BONNET HINGES @\$100.00

136
 480

holder one

\$1,450.00
 7m \$650.00
 in \$100.00 X
 one \$290.00
 set \$151.00
 twl \$165.00
 in \$200.00 X
 \$23,428.00

161

(10%)

S.NETT ITEM

1PC BONNET FIBRE
 1SET FRONT BUMPER CLIPS
 1BOL RADIATOR COOLANT
 1PC FRONT LICENCE PLATE
 1PC REAR LICENCE PLATE
 1PC REAR END PANEL SEALANT
 1SET REAR BUMPER CLIPS
 1SET REAR BUMPER REVERSE SENSOR

one \$1,800.00 650 s/w
 one \$50.00 30
 one \$50.00 20
 one \$50.00 40
 in \$50.00 X
 one \$50.00 ✓
 one \$50.00 30
 modification \$200.00 200

TO CHECK WIRING
 TO DISMANTLE & REFIX REAR REVERSE SENSOR
 TO DISMANTLE & REFIX CUSHION UPHOLSTERY
 TO DISMANTLE & REPLACED REAR EXHAUST
 TO REFILL AIR CON GAS
 TO SPRAY ANTI RUST PROOFING
 TO DIAGNOSTIC & REPROGRAMME SYSTEM
 LABOUR CHARGE
 TO PUTTY & SPRAY PAINTING

\$50.00 20
 \$80.00 50
 \$120.00 80
 in \$100.00 X
 \$100.00 ✓
 \$120.00 100
 in \$180.00 X
 \$2,800.00 1500
 \$2,800.00 1800
 TOTAL \$32,078.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

7-14274
 102
 12866.6
 1020
 3630
 17576.60