Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Muhd Ashik B Madi 06 Jun 2023 Date:

Preliminary Advice

Insured Vehicle No : SLL1320P

TP Vehicle No : SMX3521M Accident Date : 19/05/2023 Make : MITSUBISHI ATTRAGE Assignment Date : 30/05/2023

Date of Inspection : 30/05/2023 Est. Duration of Repair : 3

: LIAN HER MOTORS Inspection At

BLK 5038 ANG MO KIO INDUSTRIAL PARK 2,

#01-405 SINGAPORE 569541

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,156.30
Revised Amount	:S\$	3,820.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,820.50
Lump Sum Repair	:S\$	3.000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	83,000.00
COE / PARF Rebate	:S\$	34,515.00

Salvage Value :S\$

Margin for Repair :S\$ 48,485.00

Remarks

()	The vehicle is economical for repair
()	The vehicle is not economical for repair
()	Part-by-Part repair
(X)	Lump Sum repair

The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (X) (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.