

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/P 91082728

Iaxis Leasing & Rental Pte Ltd
5 Yishun Industrial St 1
#01-18 North Spring Bizhub
Singapore 768161

Vehicle No : SMX 3521 M
Make : Mitsubishi Attrage
Year : 2019

Not Notation
1/1/19 @ 3000h
Repair After Paint
3 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front o/s headlamp assy	1208	GT	\$1,299.00	✓
1 pc	Front support panel air garnish	photo	PC	\$155.00	X
1 pc	Front grille		PC	\$555.00	X
1 pc	Front grille emblem		PC	\$55.00	X
1 pc	Front grille top garnish		PC	\$155.00	X
1 pc	Front no plate garnish		PC	\$195.00	X
1 pc	Front bumper		CM	\$703.00	✓
1 pc	Front bumper reinforcement	photo 345	PC	\$466.00	✓
1 pc	Front bumper lower grille	photo	PC	\$155.00	✓
1 pc	Front o/s bumper side retainer		PC	\$55.00	✓
1 pc	Front o/s bumper chrome moulding - upper		CM	\$105.00	✓
1 pc	Front o/s bumper chrome moulding - lower		CM	\$205.00	✓
1 pc	Front o/s bumper fog lamp assy	photo	PC	\$279.00	✓
1 pc	Front o/s bumper fog lamp garnish	photo	PC	\$85.00	✓
1 pc	Front windscreen washer tank motor		PC	\$85.00	X
1 pc	Front windscreen washer tank	photo	PC	\$105.00	✓
				\$4,502.00	
				Less 10 %	\$450.20
					\$4,051.80

S. Nett Item

15 pcs	Clip	PC	\$2.00	\$30.00	✓
--------	------	----	--------	---------	---

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$900.00	400l
To putty & spray paint on accident affected portion.	\$900.00	450l
balance c/f	\$5,881.80	


LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



MX 3521 M

balance b/f \$5,881.80

Labour Charges

To spray anti rust on accident affected portion.

nn \$100.00 *X*

Check and reconnect wiring.

Total \$35.00 *201*
\$6,016.80