



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS3/SMR21009820/Dny3e2-1 Date: 06/06/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 1955H	Veh. Inspected	FBM 7681X
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/09/21/2035	Excess (\$)	0.00
Assign From	ANA	Assign Date	29/05/2023
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. S1000 XR	c.c	999
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WB10D0304GZ444579	Colour	RED
Odometer	28096 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70Z R17	MICHELIN	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	190/55Z R17	MICHELIN	4 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/09/2021	Inspection Date	22/09/2021
Survey held at	20 Bukit Batok Crescent #01-19		
Repairer	PRIMERO RACING		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	