

ASS. REC. BY:

REF:

HSB/ 23005427/KP

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / GIA & EM not ready

6/6 112p @ 2050L Cohn

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$

Interview (\$

Tech Invs (\$

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

☐

Prel. Report

☐

Final Report

TSR AUTOMOTIVE PTE LTD
160, SIN MING DRIVE, SIN MING AUTOCITY
06-15 SINGAPORE 575722
tsrteamworks2022@gmail.com / 90030857

Not Authorized
21 May @ 2050h
Review After Paint
3 days

Date : 28 May 2023

QUOTATION - OWN DAMAGE CLAIM

HSBC LIFE (SINGAPORE) PTE LTD

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 28 May 2023

VEH. No : SKP 8687 B 216I

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : INCOME INSURANCE

QTY	ITEM	AMOUNT	CONDITION
YOUR INSURE : SHD 4509 H			
1	TAILGATE	REPAIR	
1	REAR BUMPER 1050	\$ Bu 2,258.00	✓
2	REAR BUMPER SENSORS @ 235	\$ Mr 656.00	✓
4	REAR BUMPER SENSOR BRACKETS	\$ L 448.00	X
1	REAR BUMPER REINFORCEMENT	\$ A 785.00	X
1	REAR BUMPER CENTER BRACKET	\$ L 585.60	X
2	REAR BUMPER SIDE BRACKETS	\$ L 840.00	X
1	REAR BUMPER OUTER CHROME 110	\$ Rd 442.00	✓
1	REAR EXHAUST	REPAIR	
1	REAR EXHAUST HEAT SHIELD CENTER	\$ A 520.00	X
1	REAR EXHAUST CHROME END 180	\$ Rd 280.00	✓
1	END PANEL	REPAIR	
TOTAL PARTS :		\$ 6,814.60	
LESS 5%		\$ 340.73	
TOTAL LIST PARTS :		\$ 6,473.87	
TOTAL PARTS PRICE :		\$ 6,473.87	
AMOUNT BRING FORWARD		\$ 6,473.87	
Labour charges		\$ 600.00	400
Replace sensors, check wiring system, for rear affected area		\$ 180.00	60
Anti rust		\$ 120.00	X
To do computer setting programme after repair		\$ 180.00	X
To do spray painting on affected area inner outer		\$ 500.00	400
TOTAL LABOUR :		\$ 1,580.00	
GRAND TOTAL PARTS & LABOUR :		\$ 8,053.87	

KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Must be resurveyed and
subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: