

ASS. REC. BY:

REF:

GRB/2300543011cp

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$65k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: M / S / R / Im / STD A / R / Im or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/6 11:00pm @ 1550hr Cuhw

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

) \$ - RS. \$

) Fuel

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email:

tanpw@cdge.com.sg;kelvinsukwen@cdge.com.sg;oisunpin@cdge.com.sg;joharibh@sparkcarcare.com;kristytay@sparkcarcare.com

TP INSURER: India International Insurance Pte Ltd (HQ)
SINGAPORE POST LIMITED

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	16/05/2023
Vehicle Reg. No.:	GBK1021B	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	NISSAN NV350, 2.5 (A)	Vehicle Reg. Date:	26/12/2019
Vehicle Colour:	BLUE	Chassis No:	YD25057820B
Engine No:	JN1MC2E26Z0031625		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	<i>5/4 days</i>		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

*Not with a
11/12/2023
Repair After Rain
4 days*

COST OF CLAIMS

	Amount
Parts	5,439.60
Miscellaneous Items	381.00
Labour	1,580.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,400.60
+ GST 8.00% (S\$)	592.05
Nett Amount (S\$)	7,992.65

This claim is handled by: SU KHAI WEN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 23 May 2023)

Parts: N/A NISSAN NV350 2.5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/GBK1021B/23/05/2023 17:37

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	0.00	0.00	*735.00 F ✓
2	1		*REAR BUMPER CLIPS	0.00	0.00	*65.00 F ✓
3	1		*REAR BUMPER RETAINER - LH	0.00	0.00	*20.00 F X
4	1		*REVERSE SENSOR	0.00	0.00	*300.00 F X
5	1		*REAR TAILGATE	0.00	0.00	*2,000.00 F X
6	1		*REAR TAILGATE WEATHERSTRIP	0.00	0.00	*166.00 F X
7	1		*LHR FENDER	0.00	0.00	*2,310.00 F X
8	1		*LHR MUDFLAP	0.00	0.00	*166.00 F X
9	1		*TAILLAMP - LH	0.00	0.00	*275.00 F ✓
10	1		*TAILLAMP CLIPS	0.00	0.00	*7.00 F ✓

F=Franchise part.

Sub Total (S\$) 6,044.00

- Add. Disc. on L,N Items 10.00% (S\$) 604.40

Total Parts (S\$) 5,439.60

ComfortDelGro Engineering Pte Ltd/GBK1021B/23/05/2023 17:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	70KM/H	20.00 ✓
2	1	LIVERY	350.00 150/2 ✓
3	1	OD/TP Case (Insurer)	NEC 11.00 ✓
Sub Total (S\$)			381.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO PANEL BEAT TAILGATE, REAR END PANEL, LHR FENDER	New	750.00 400 ✓
2	TO PUTTY, RESPRAY REAR BUMPER, LHR FENDER, REAR TAILGATE	New	750.00 400 ✓
3	CHECK WIRING	New	80.00 20 ✓
Gross Labour Cost (S\$)			1,580.00

ComfortDelGro Engineering Pte Ltd/GBK1021B/23/05/2023 17:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >