

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

LKK

TP INSURER: India International Insurance Pte Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	24/05/2023
Vehicle Reg. No.:	SHA3381E	Driveable?	
Party At Fault:	UNKNOWN		

Make/Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Vehicle Reg. Date:	30/10/2018
Vehicle Colour:	BLUE	Chassis No:	KMHC851CVKU114933
Engine No:	G4LEJU111580		
Odometer:	407226 KM		

Paint Type:	
List Item Discount:	20.00 %
Total Loss?	NO
Est. Duration of Repair (day)	3

Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)
-------------------	--

COST OF CLAIMS	Amount
Parts	1,709.28
Miscellaneous Items	11.00
Labour	1,020.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,740.28
+ GST 8.00% (S\$)	219.22
Nett Amount (S\$)	2,959.50

This claim is handled by: CHIANG LIAT CHOON

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 May 2023)

Parts: 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA3381E/29/05/2023 11:03

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	fr ✓ *459.40 FL
2	1		*REAR BUMPER SIDE BRACKET LH	20.00	0.00	de ✓ *55.80 FL
3	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	de ✓ *451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	? ✓ *394.80 FL
5	1		*REAR BUMPER REINFORCEMENT STAY LH	20.00	0.00	? ✓ *138.10 FL
6	1		*REAR BUMPER REFLECTOR LH	20.00	0.00	art ✓ *41.45 FL
7	1		*REAR BUMPER TOW HOOK COVER LH	20.00	0.00	art ✓ *98.80 FL
8	10		*REAR BUMPER CLIPS	20.00	0.00	net ✓ *22.00 FL
9	1		*REAR BUMPER REVERSE SENSOR	0	0.00	? ✓ *180.00 FS
10	2		*REAR FENDER ADVERTISEMENT STICKER	0	0.00	net ✓ *200.00 FS

F=Franchise part. S=SpocNett. L=ListItemDisc.

Sub Total (S\$) 2,041.60

- List Item Discount on L Items (S\$) 332.32

Total Parts (S\$) 1,709.28

ComfortDelGro Engineering Pte Ltd/SHA3381E/29/05/2023 11:03. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	250	600.00
2	SPRAY PAINTING	New	250	300.00
3	CHECK WIRING AND LIGHTING	New	X	60.00
4	REMOVE/REFIX REVESE SENSOR	New	30	60.00
Gross Labour Cost (S\$)				1,020.00

ComfortDelGro Engineering Pte Ltd/SHA3381E/29/05/2023 11:03. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanfhi 97495749
WSP 29/5/23 2:43pm
L/S Resurvey after repair
- 2 days
Tanfhi & Muanth...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: