

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305556021
Date : 29.05.22
Time of Fax : /

Via Fax : EMAIL
Your Insured : SNJ 8218T
Date of Acc : 28.05.22

Attn: Motor Claims Department

Allianz

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH C 21283

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
◆ <u>Chiang Liat Choon</u>	<u>Tel: 6214 8314 or HP: 9296 6006</u>

chianglc@cdege.com.sg
Fax no. 6546 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President
Taxi Accident Repair

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHC2128S
 Make : TOYOTA
 Model : PRIUS G4
 DOA : 28.05.2023

Date : 29.05.2023
 Insurance: ALLIANZ
 MVA : CHIANG
 Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			\$1,054.71
1	REAR TRUNK LID LOGO (PRIUS)			\$60.80
1	REAR TRUNK LID LOGO (HYBRID)			\$52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$52.90
1	REAR TRUNK COVER			\$1,303.29
1	REAR WINDSCREEN GLASS W/MOULDING			\$1,884.32
1	REAR TRUNK LID GLASS W/MOULDING			\$1,787.79
1	REAR BUMPER			\$551.89
1	REAR BUMPER UNDER COVER			\$654.96
1	REAR BUMPER REINFORCEMENT			\$378.32
1	REAR BUMPER SIDE RETAINER LH		\$112.70	\$112.70
1	REAR BUMPER UNDER COVER CENTRE			\$252.00
1	REAR BUMPER REFLECTOR /RH		\$55.00	\$55.00
1	REAR END PANEL			\$738.96
1	REAR END PANEL GARNISH			\$165.80
1	TAIL LAMP UPPER LH		\$557.90	\$557.90
1	TAIL LAMP LOWER LH		\$570.00	\$570.00
10	REAR BUMPER CLIPS			\$22.00
SUB TOTAL				\$10,255.74
LESS 25%				\$2,563.94
DISCOUNTED TOTAL				\$7,691.81
1	REAR TRUNK LID APPS STICKER			\$40.00
2	REAR TRUNK LID COMFORT & TEL NO. STICKER		\$30.00	\$60.00
2	REAR FENDER ADVERTISEMENT LH/RH		\$100.00	\$200.00
1	REAR BUMPER ADVERTISEMENT			\$50.00
1	REAR BUMPER REVERSE SENSOR			\$135.70
				\$485.70
<u>Labour Charge</u>				
	Panel Beating			\$1,050.00
	Spray Painting Charge			\$800.00
	Wiring Charge			\$60.00
	Remove/Refix windscreen and lower glass			\$180.00
	Tuff Kote			\$90.00
	Towing Fee			\$60.00
	Remove/Refix Reverse Sensor			\$60.00
TOTAL LABOUR				\$2,300.00

	ESTIMATE TOTAL			\$10,477.51

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.