

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SPF 23005438/Uny3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA5303X

at Workshop m/s 7LM

of _____

Insured: QX5074B

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 84212

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: LT A20020

Veh No: SLA5303X Yr Regn: 02/03/16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Murder c.c. 1496

Colour: wh. tp A/C: Insured / Std / NI / NA

Sp. Reading: 166340 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU11107472

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / VRim or

Tyre Size: F: 215/60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 18/05/23 D.O.I. 27/5/23

Survey held at 24

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 06/06/23

near bumper cracked

2/5 \$3400 in hand MR Ten (Red. \$ 5552.72, 62%)

repair range \$3400 - \$4k

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6051
Vehicle Details	
Vehicle No.:	SLA5303X
Vehicle to be Exported:	No
Intended Deregistration Date:	24 May 2023
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15B4027476
Chassis No.:	RU11107472
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,730.00
Original Registration Date:	02 Mar 2016
First Registration Date:	02 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$9,730.00 486.5
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Mar 2026
PARF Rebate Amount:	\$5,838.00
Intended COE Rebate Details	
COE Expiry Date:	01 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,301.00
COE Rebate Amount:	\$14,182.00
Total Rebate Amount:	\$20,020.00

The information contained herein is correct as at 24 May 2023

OK

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Low Interest Rate In-House Loan by GV Cars Financing



\$0 Downpayment. Loan by GV
Cars Financing at 3.28% p.a.
Low Interest Rate
GV Automobile Centre StarAd

Lake View Credit Pte Ltd

- > Low price
- > Specialist
- > Easy loan
- > All terms

« Back (1 2 3 4 5 6) Next »

Sort by Date Posted


102 vehicles



Vezel

Any Category

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh
Search Selection	Vezel		Any	Any	2016	Any	Any	
	Honda	Vezel 1.5A X	\$53,800	\$14,720 /yr	13-Sep-2016	1,496 cc	69,000 km	
Low Mileage Low Ownership With Warranty, Safe Unit To Tide Over The High COE Trend, Hassle Free Loan And Insurance Processes Han...								
✔ This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More								
Victory Cars Trading Pte Ltd								
Posted: 24-May-2023								
	Honda	Vezel 1.5A X Honda Sensing	\$53,888	\$14,340 /yr	19-Oct-2016	1,496 cc	70,000 km	
New arrival. Well maintained interior too. Bank loan and in house loan available. Call now for immediate viewing arrangement.								
Posted: 24-May-2023								
	Honda	Vezel 1.5A X	\$50,888	\$13,940 /yr	19-Aug-2016	1,496 cc	144,397 km	
The Vezel is by far one of the most popular crossover SUVs. The styling is still very modern despite its age, and upkeep is completely wo...								
Carro								
Posted: 23-May-2023								
	Honda	Vezel Hybrid 1.5A X	\$56,800	\$17,390 /yr	08-Jul-2016	1,496 cc	88,750 km	
Fuel Type: Petrol-Electric								
Beautiful Original Metallic Pearl White, 1 Careful Owner, Not PHV Car, Well Maintain By Previous Owner, Under Warranty, Seldom Used, A...								
Jia Leong Trading Enterprise								
Posted: 23-May-2023								
	Selling your Honda Vezel?							
Receive \$3,000 more than trade-in when you sell your Honda Vezel with Sgcarmart Quotz.								
Get Free Valuation with Sgcarmart Quotz								

Compare

TLM Automobile Pte Ltd

1 Defu Lane 6 Singapore 539365

UEN number: 202244624K

Ms Sukarti Binte Dawami

Estimate To Repair

SLA5303X - Honda Vezel 1.5X CVT

Chassis No : RU11107472

Not Allowed
her
mercy

1/5 \$3400

take place After 1st

15/23

5 days
take place After 1st

Third Party Insurer: SPF

Date of accident: 18 May 2023

Date: 23 May 2023

S/No	Quantity	Description	Amount
LIST ITEMS			
1	1 pc	tailgate lid Vezel badge <i>neu</i>	\$ 42.90
2	1 pc	n/s tailgate lid reflector <i>11</i>	\$ 284.60
3	1 pc	tailgate lid lock top <i>11</i>	\$ 274.90
4	1 pc	rear end panel <i>panel</i> <i>R</i>	\$ 415.90
5	1 pc	rear end panel inner trim <i>11</i>	\$ 286.80
6	6 ps	rear end panel inner trim clips @ \$5.20 <i>11</i>	\$ 31.20
7	1 pc	n/s rear bumper <i>To 11</i>	\$ 762.70
8	1 pc	n/s rear bumper scare screw <i>11</i>	\$ 24.00
9	1 pc	n/s rear bumper reflector <i>11</i>	\$ 248.40
10	1 pc	n/s rear bumper side <i>D 11</i>	\$ 279.20
11	1 pc	n/s rear bumper side retainer <i>one</i>	\$ 41.50
12	8 ps	rear bumper clips @ \$5.20 <i>neu</i>	\$ 41.60
13	1 pc	n/s rear lamp <i>5 11</i>	\$ 449.10
14	4 ps	n/s rear lamp clip holder @ \$12.00 <i>11</i>	\$ 48.00
15	1 pc	n/s rear lamp panel <i>R</i>	\$ 275.30
16	1 pc	n/s rear lower diffuser <i>D 11</i> <i>348.20</i>	\$ 550.00
17	6 ps	rear lower diffuser clips @ \$3.00 <i>neu</i>	\$ 18.00
18	1 pc	rear buzzer sensor <i>11</i>	\$ 108.20
19	1 pc	rear bumper center <i>Repair</i>	\$ 455.20
20	1 pc	n/s rear mudguard under cloth <i>To 11</i>	\$ 182.60
21	1 pc	n/s rear mudguard outer protector <i>To 11</i>	\$ 240.80
22	1 pc	n/s rear mudguard <i>neu</i>	\$ 895.00
23	1 pc	n/s rear mudguard inner trim <i>11</i>	\$ 335.00
			\$ 6,290.90
		Less 20%	\$ 1,258.18
			\$ 5,032.72
SPECIAL NETT ITEMS			
24	1 set	rear bumper parking sensor <i>11</i>	\$ 800.00
25	1 tube	rear windscreen sealant <i>11</i>	\$ 80.00
			\$ 880.00
		Balance c/f	\$ 5,912.72

TLM Automobile Pte Ltd
1 Defu Lane 6 Singapore 539365
UEN number: 202244624K

Ms Sukarti Binte Dawami

Third Party Insurer : SPF
Date of accident : 18.05.2023
Date: 23.05.2023

Estimate To Repair
SLA5303X - Honda Vezel 1.5X CVT
Chassis No : RU11107472

S/No	Quantity	Description	Amount
		Balance b/f	\$ 5,912.72
		<u>LABOUR & MISC. CHARGES</u>	
1		To reinstall of front and rear bumper parking sensor.	\$ 80.00
2		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 200.00
3		To remove and refit rear windscreen glass.	\$ 140.00
4		To transfer of tailgate fittings, fixure and perform waterseepage test.	\$ 100.00
5		To check electrical lighting concerned.	\$ 120.00
6		Panel beating, knocking and straighten the necessary portion. Remove and renewal of parts, adjust and realign the same.	\$ 1,200.00
7		Putty and spray painting of the affected portion.	\$ 1,200.00
			\$ 3,040.00
		Grand Total	\$ 8,952.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed

is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 3301.60
202
2641.28
1630
4271.28
202
3417