



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S2M04B84

Date: 01<sup>st</sup> August 2023

Our Ref: CS3/ASM22009193/Tcp3m4-1

**M/s HSBC Life (Singapore) Pte Ltd**

10 Marina Boulevard  
#48-01 Marina Bay Financial Centre Tower 2  
Singapore 018983  
(The Motor Claims Department)

Attn: Low Garnet

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJR 3094X  
INSURED VEHICLE: SNE 1497B  
ACCIDENT DATE: 16/09/2022**

We thank you for your instruction on 29/05/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJR 3094X from Allied Auto Appraisal.
- b) Singapore Accident Statement of Vehicles SJR 3094X and SNE 1497B.
- c) Police Report of Vehicle SNE 1497B.
- d) Final Repair Bill of SJR 3094X from D's Graffiti Concepts Pte Ltd.
- e) Colour damaged vehicle photographs of SJR 3094X.

Pre-Repair Inspection Date: 19/09/2022 at M/s D's Graffiti Concepts Pte Ltd, 8 Kaki Bukit Avenue 4 #02-24 Premier @ Kaki Bukit, Singapore 415875.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJR 3094X
Make & Model	: Toyota Camry 2.4 Auto Abs Airbag
Year of Registration	: 2009
Chassis Number	: MR053BK4007034607
Engine Capacity	: 2362 cc

- 2. We recommend that the repairs of the entire damage require about 14 (Fourteen) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.