

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET
IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

EST/QUOTE NO. SQ008159

DATE 23/05/2023

ACCIDENT DATE : 20/05/2023

VEHICLE NO : SKR7225Y

CHASSIS/ENG.NO : ZSU600032453

VEHICLE MODEL : TOYOTA HARRIER

CLAIM NO :

POLICY NO :

REMARK : 7225 1114 TP AGST
SLT8052A

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER <i>de/</i>	1,817.20	25	1,362.90	1,362.90
2	1	PC	REAR BUMPER LOWER <i>de/</i>	481.90	25	361.43	361.43
3	1 <i>2</i>	PC	REAR BUMPER RETAINER <i>RT m/</i>	171.10	25	128.32	256.64
4	1	PC	REAR BUMPER UPP BRACKET RH <i>m/</i>	182.25	25	136.69	136.69
5	1	PC	REAR BUMPER LWR SIDE REFLECTOR F <i>cat</i>	181.90	25	136.43	136.43
6	1	PC	REAR BUMPER SPONGE <i>ca/</i>	271.70	25	203.78	203.78
7	1	PC	REAR BOOT LID <i>st/</i>	1,718.25	25	1,288.69	1,288.69
8	1	PC	REAR BOOT HARRIER STICKER <i>m/</i>	121.70	25	91.28	91.28
9	1	PC	REAR BOOT WEATHERSTRIP <i>m/</i>	571.10	25	428.32	428.32
10	1	PC	REAR BOOT LAMP RH <i>X</i>	781.90	25	586.42	586.42
11	1	PC	REAR TAILLAMP RH <i>X</i>	561.10	25	420.82	420.82
12	3	PC	REAR WINDSCREEN MOULDING <i>m/</i>	180.00	25	135.00	405.00
13	1	PC	REAR END PANEL <i>st/</i>	971.10	25	728.33	728.33
14	1	PC	REAR END PANEL TOP GARNISH <i>?</i>	672.75	25	504.56	504.56
15	1	PC	REAR EXHAUST <i>st/</i>	1,217.80	25	913.35	913.35
						SUB-TOTAL:	7,824.64
** NETT PRICE **							
1	10	PC	REAR BUMPER CLIPS <i>m/</i>	4.00		4.00	40.00
						SUB-TOTAL	40.00

SAM

PAGE: 1 of 2

8%

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET
IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

EST/QUOTE NO. SQ008159

DATE 23/05/2023

ACCIDENT DATE : 20/05/2023

VEHICLE NO : SKR7225Y

CHASSIS/ENG.NO : ZSU600032453

VEHICLE MODEL : TOYOTA HARRIER

CLAIM NO :

POLICY NO :

REMARK : 7225INDIA - TP AGST
SLT8052A

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** SPECIAL NETT PRICE **							
1	1	PC	REAR WINDSCREEN SEALANT	40.00		40.00	40.00
SUB-TOTAL							40.00

**** WORK LABOUR ****

TO KNOCK RR FENDER RH, WELD, REMOVE & FIX ON ABOVE PARTS

TO PUTTY & SPRAY PAINTING ON AFFECTE AREAS

TO CHECK WIRING

APPLY ANTI RUST COATING

TO REMOVE & REFIX REAR WINDSCREEN

DIAGNOSE & RESET FAULT CODE

TO REMOVE & REFIX TRIMS & UPHOLSTERY

TO REMOVE & FIX REAR EXHAUST

700	850.00	850.00
800	900.00	900.00
	30.00	30.00
60	120.00	120.00
120	150.00	150.00
150	200.00	200.00
60	150.00	150.00
100	150.00	150.00
SUB-TOTAL		2,550.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SAM

PAGE: 2 of 2

SUB-TOTAL : S\$ 10,454.64
ADD GST. 8% S\$ 836.37
GRAND TOTAL : S\$ 11,291.01

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.