



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD			Ref: CS/HSB23005460/p3	
10 MARINA BOULEVARD			Date: 30/05/2023	
#48-01 MARINA BAY FINANCIAL CENTRE TOWER				
2SINGAPORE 018983			Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7680Z	Veh. Inspected	SNC 1822G	
Policy No.		Coverage (\$)	0.00	
Claim No.	S3M04MWE	Excess (\$)	0.00	
Assign From	KHOR SAW THENG	Assign Date	30/05/2023	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/05/2023	Inspection Date		
Survey held at	HUAT HOCK MOTOR WORKSHOP BLK 3012 BEDOK NORTH AVE 4 BEDOK INDUSTRIAL PARK E #01-2054 SINGAPORE 489978			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				