

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ivy Yong

Date: 01 Jun 2023

Preliminary Advice

Vehicle No	: YQ9500D	Accident Date	: 26/05/2023
Make	: TOYOTA DYNA 150	Policy No.	: DMFG23000072
Assignment Date	: 29/05/2023	Excess	: S\$500.00
Date of Inspection	: 31/05/2023	Est. Duration of Repair	: 6
Inspection At	: FORZA AUTOHAUS PTE LTD (HQ) NO.39 WOODLANDS CLOSE, #01-34/35, MEGA@WOODLANDS SINGAPORE 737856		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,488.50
Revised Amount	:S\$	3,879.50
Check Items (Estimated)	:S\$	4,334.40
Total	:S\$	8,213.90
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	100,000.00
COE / PARF Rebate	:S\$	38,062.00
Salvage Value	:S\$	
Margin for Repair	:S\$	61,938.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Lump Sum repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .