

ASS. REC. BY:

REF:

EGF 23005464/KV

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Forza

of 01-34-35

Insured: _____

Policy No. DMFG23000072

Claims No. CDMFG23001293


Sum Insured: _____ Excess: 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 2100k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: YG 9500D Yr Regn: 01, 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M):

Make: Toyota Dyna c.c. 2754

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 21958 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTHH AGV 4610K 001719

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: Falken 195R15XL R: Yokohama 155R12XL (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 26/5/23

Rear

R/Bal. 88 mm

L/Bal. 88 mm

D.O.I. 31/5/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/6/23 11:30 AM @ 3700k Cash (red 3788.50, 39%)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report1) _____
Date/Time, File Return to?

2) 9/6/23-typist

Days Of Repair: 6

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation

S + RS. \$

Fees

Others

TOTAL

Report Format: Merimen

Lump Sum H.B.t. (\$ 5700

Forza Autohaus Pte Ltd (Co.Reg.No:201833292C)

No.39 Woodlands Close, #01-34/35, Mega@Woodlands

Singapore 737856

Tel: 6278 1889 Email: enquiry@forzaauto.sg

INSURER: ERGO Insurance Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMFG23000072	Date of Loss:	26/05/2023
Vehicle Reg. No.:	YQ9500D	Driveable?	
Driver Age/Info:	64 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAK PRODUCTS & SERVICES PTE. LTD.	Contact No:	+6588208025
Driver:	TOH KIM HER		

Make/Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Vehicle Reg. Date:	27/01/2022
Vehicle Colour:	WHITE		
Engine No:	1GD8874041	Chassis No:	JHHAGV4610K001719
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10 days

Not Notified
11 Days @ 5700h
Repair After Rain
Ex @ 500

Present Location: FORZA AUTOHAUS PTE LTD (HQ)**COST OF CLAIMS**

	Amount
Parts	6,968.50
Miscellaneous Items	0.00
Labour	2,520.00
Paintwork Labour	0.00
Towing	0.00

Calculated Gross Total (S\$)	9,488.50
- Excess (S\$)	500.00
(S\$)	8,988.50
+ GST 8.00% (S\$)	719.08
Nett Amount (S\$)	9,707.58

This claim is handled by: LIEW SHAN QI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 29 May 2023)

Parts: N/A TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Forza Autohaus Pte Ltd/YQ9500D/29/05/2023 15:09

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WIPER PANEL		0.00	0.00 <i>B</i> *550.00 F ✓
2	1		*FRONT WIPER PANEL GARNISH	<i>N/A</i>	0.00	0.00 <i>B</i> *250.00 F ✗
3	1		*FRONT WIPER COVER		0.00	0.00 <i>MIT</i> *25.00 F ✓
4	1		*FRONT LOWER PANEL		0.00	0.00 <i>B</i> *520.00 F ✓
5	1		*FRONT GRILLE ASSY		0.00	0.00 <i>CM</i> *415.00 F ✓
6	1		*FRONT GRILLE ASSY BACKING		0.00	0.00 <i>Ln</i> *275.00 F ✗
7	1		*FRONT GRILLE LOGO EMBLEM		0.00	0.00 <i>Ln</i> *60.00 F ✓
8	2		*FRONT HEADLAMP L/R	<i>mycm</i>	0.00	0.00 *1,240.00 F ✓
9	1		*FRONT BUMPER		0.00	0.00 <i>B</i> *575.00 F ✓
10	2		*FRONT BUMPER BRACKET L/R	<i>B</i>	0.00	0.00 *190.00 F ✓
11	1		*COOLING COIL ASSY	<i>CM</i>	0.00	0.00 *1,250.00 F ✓
12	1		*AIR CON BLOWER COMPLETE	<i>Ln</i>	0.00	0.00 *680.00 F ✗
13	1		*FRONT BUMPER INNER SUPPORT		0.00	0.00 <i>B</i> *305.00 F ✓

F=Franchise part.

Sub Total (S\$)	6,335.00
+ Margin on L,N Items 10.00% (S\$)	633.50
Total Parts (S\$)	6,968.50

Forza Autohaus Pte Ltd/YQ9500D/29/05/2023 15:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification/alterations
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			<i>7001</i>
1	TO PROVIDE LABOUR , WORKSMANSHIP TO CHANGE THE ABOVE DAMAGE BODY PART, REPAIR, RE-ALIGN BODY STRCUTURE, BODY ALIGNMENTS AND DAMAGES CONSISTENT TO ACCIDENT	New	1,200.00
2	TO CHECK ON ELECTIRCAL WIRING AND HEADLAMP FOCUSING	New	<i>201</i> 120.00
3	TO RESPRAY PAINTING ON THE CHANGE BODY PART, REPAIR PORTION CONSISTENT TO ACCIDENT	New	<i>8001</i> 1,200.00
Gross Labour Cost (S\$)			2,520.00

Forza Autohaus Pte Ltd/YQ9500D/29/05/2023 15:09. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >