

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: HL Assurance Pte Ltd  
11 Keppel Road  
#11-01 ABI Plaza  
Singapore 089057From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Romeo Jonnalyn Alaan

Date: 05 Jun 2023

**Preliminary Advice**

Vehicle No	: SLS1682H	Accident Date	: 25/05/2023
Make	: TOYOTA HARRIER	Policy No.	: MP314066
Assignment Date	: 30/05/2023	Excess	: S\$375.00
Date of Inspection	: 05/06/2023	Est. Duration of Repair	: 6
Inspection At	: AH LIM MOTOR COMPANY (SIN MING) 176 SIN MING DRIVE #05-12, SIN MING AUTOCARE SINGAPORE 575721		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,792.25
Revised Amount	:S\$	6,209.15
Check Items (Estimated)	:S\$	1,761.10
Total	:S\$	7,970.25

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	89,000.00
COE / PARF Rebate	:S\$	43,529.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,471.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.