

ASS. REC. BY:

REF:

HLV 23005466/Kny3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/7 86922-15 Caber (Red. \$ 2870.10, 2970)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	992B
Vehicle Details	
Vehicle No.:	SLS1682H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 May 2023
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER PREMIUM 2.0 A
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	3ZRB769810
Chassis No.:	ZSU600076537
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$30,885.00
Original Registration Date:	24 Aug 2017
First Registration Date:	24 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$30,239.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Aug 2027
PARF Rebate Amount:	\$21,167.00
Intended COE Rebate Details	
COE Expiry Date:	23 Aug 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$52,751.00
COE Rebate Amount:	\$22,362.00
Total Rebate Amount:	\$43,529.00

The information contained herein is correct as at 26 May 2023

OK

AH LIM MOTOR COMPANY

176 SIN MING DRIVE #05-12
 SIN MING AUTOCARE Singapore 575721
 Tel: 64563637 Fax: Email:
 GST Reg No: M9-0009639-E

SURVEYOR COPY

INSURER: HL Assurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/HL
Policy No:	MP314066	Date of Loss:	25/05/2023
Vehicle Reg. No.:	SLS1682H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LAM HIN CHEW	Contact No:	+6582009361
Driver:	LAM HIN CHEW		

Make/Model:	TOYOTA HARRIER, 2.0 (A)	Vehicle Reg. Date:	24/08/2017
Vehicle Colour:	BLACK	Chassis No:	ZSU600076537
Engine No:	3ZRB769810		
Odometer:	0 KM		

Paint Type:
 Total Loss?
 Est. Duration of Repair (day)

NO

86 days

Not with air
Repair B4 paint
Ex @ 375k

Remarks: WORKSHOP HANDLER- MEILI TAN TEL: 6456 3637 EMAIL : MEILI@ALMSM.COM.SG VEHICLE IS CURRENTLY NOT IN THE WORKSHOP
 Present Location: AH LIM MOTOR COMPANY (SIN MING)

COST OF CLAIMS

	Amount
Parts	6,942.25
Miscellaneous Items	0.00
Labour	2,850.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	9,792.25
+ GST 8.00% (\$)	783.38
Nett Amount (\$)	10,575.63

This claim is handled by: MEILI TAN-SIN MING BRANCH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AH LIM MOTOR COMPANY
 (SIN MING BRANCH)
 176, Sin Ming Drive, #05-12
 Sin Ming Autocare, Singapore 575721
 Tel: 6456 3637 Fax: 6456 3686

SURVEYOR COPY

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 May 2023)

Parts: M1-SUV TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLS1682H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET	Buc 0.00	0.00	*450.00 F	✓
2	1		*FRONT BONNET CHROME MOULDING	CM 0.00	0.00	*105.00 F	✓
3	2		*HEADLAMP LH/RH	m3 CM 0.00	0.00	*1,800.00 F	✓
4	1		*RADIATOR GRILLE	CM Buc 0.00	0.00	*200.00 F	✓
5	1		*FRONT BUMPER	Di 0.00	0.00	*250.00 F	✓
6	2		*FRONT BUMPER SIDE RETAINER LH/RH	Di 0.00	0.00	*90.00 F	✓
7	15		*FRONT BUMPER CLIP	Di 0.00	0.00	*22.50 F	✓
8	1		*FRONT BUMPER REINFORCEMENT	Di 0.00	0.00	*160.00 F	✓
9	1		*FRONT BUMPER SPONGE	CM 0.00	0.00	*45.00 F	✓
10	1		*FRONT BUMPER BEAM CENTRE	R 0.00	0.00	*100.00 F	✓
11	2		*FRONT BUMPER BEAM SIDE LH/RH	R 0.00	0.00	*96.00 F	X
12	1		*FRONT BUMPER LOWER GRILLE	Di 0.00	0.00	*105.00 F	✓
13	2		*FRONT BUMPER TOWING COVER LH/RH	Di 0.00	0.00	*30.00 F	X
14	1		*FRONT BUMPER LOWER GARNISH	Di 0.00	0.00	*120.00 F	X
15	1		*FRONT BUMPER UNDER TRAY	Di 0.00	0.00	*75.00 F	X
16	2		*FRONT BUMPER SPONGE SIDE LH/RH	Di 0.00	0.00	*50.00 F	X
17	2		*FRONT FENDER LH/RH	Buc 0.00	0.00	*530.00 F	✓
18	1		*FRONT BONNET LOCK	Di 0.00	0.00	*65.00 F	✓
19	1		*RADIATOR SUPPORT PANEL	R 0.00	0.00	*320.00 F	X
20	1		*BRACE PANEL	R 0.00	0.00	*95.00 F	✓
21	16		*FENDER COWLING CLIP	Di 0.00	0.00	*24.00 F	✓
22	1		*SUPPORT PANEL TOP COVER	Di 0.00	0.00	*140.00 F	X
23	10		*SUPPORT PANEL TOP COVER CLIP	Di 0.00	0.00	*15.00 F	✓
24	2		*RADIATOR SIDE AIR GUIDE UPPER OUTER LH/RH	Di 0.00	0.00	*120.00 F	X
25	2		*RADIATOR SIDE AIR GUIDE INNER LH/RH	Di 0.00	0.00	*110.00 F	X
26	1		*AIR CON CONDENSER	R 0.00	0.00	*550.00 F	✓
27	1		*RADIATOR	Di 0.00	0.00	*580.00 F	X
28	1		*RADIATOR COOLANT	Di 0.00	0.00	*35.00 FS	X
29	1		*FRONT NO PLATE	R 0.00	0.00	*35.00 FS	✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 6,317.50

+ Margin on L,N Items 10.00% (\$\$) 624.75

Total Parts (\$\$) 6,942.25

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

AH LIM MOTOR COMPANY
(SIN MING BRANCH)
176, Sin Ming Drive, #05-12
Sin Ming Autocare, Singapore 575721
Tel: 6456 3637 Fax: 6456 3686

No	Particulars	Lab.Type	Amount
			SURVEYOR COPY
<u>Labour Items</u>			
1	TO CHECK WIRING AND REFOCUS HEADLAMP	New	30.00
2	TO DISMANTLE AND REFIT AIRCON CONDENSER AND REFILL WITH AIR CON GAS	New	120.00
3	TO DISMANTLE AND REPLACE DAMAGE PARTS TO CUT; KNOCK AND WELD FROM SUPPORT PANEL KNOCK; ALIGN AND REPAIR FRONT AFFECTED AREA	New	1,100.00
4	TO SPRAY BONNET INNER / OUTER; FRONT FENDER LH; FRONT FENDER RH; FRONT BUMPER; FRONT DOOR LH; FRONT DOOR RH AND FRONT SUPPORT PANEL	New	1,600.00
Gross Labour Cost (S\$)			2,850.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

AH LIM MOTOR COMPANY
(SIN MING BRANCH)
176, Sin Ming Drive, #05-12
Sin Ming Autocare, Singapore 575721
Tel: 6456 3637 Fax: 6456 3686

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: