

AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721

TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg

GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : HL ASSURANCE PTE LTD

11 KEPPEL ROAD

#11-01 ABI PLAZA

SINGAPORE 089057

TEL: 67020202

ATTN: Motor Claim Department

Your Ref No: SLS1682H

Claim Type: Own Damage

Accident Date: 25/05/2023

Claim No: MCS1900907

Ref No: MFS1900821

Date: 25 Jul 2023

Policy No: MP314066

Vel Reg No: SLS1682H

Make/Model: TOYOTA HARRIER

Chassis No: ZSU600076537

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization): SLS1682H

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
SPARE PARTS				
1 FRONT BONNET		1 PC	450.00	
2 FRONT BONNET CHROME MOULDING		1 PC	105.00	
3 HEADLAMP LH/RH		2 PC	1,800.00	
4 RADIATOR GRILLE		1 PC	200.00	
5 FRONT BUMPER		1 PC	250.00	
6 FRONT BUMPER SIDE RETAINER LH/RH		2 PC	90.00	
7 FRONT BUMPER CLIP		15 PC	22.50	
8 FRONT BUMPER REINFORCEMENT		1 PC	160.00	
9 FRONT BUMPER SPONGE		1 PC	45.00	
10 FRONT BUMPER BEAM CENTRE		1 PC	100.00	
11 FRONT BUMPER LOWER GRILLE		1 PC	105.00	
12 FRONT FENDER LH/RH		2 PC	530.00	
13 FRONT BONNET LOCK		1 PC	65.00	
14 BRACE PANEL		1 PC	95.00	
15 FENDER COWLING CLIP		16 PC	24.00	
16 SUPPORT PANEL TOP COVER CLIP		10 PC	15.00	
17 AIR CON CONDENSER		1 PC	550.00	
			4,606.50	
	Add 10%		460.65	5,067.15
Special Nett				
18 FRONT NO PLATE		1 PC	35.00	35.00
LABOUR				
19 TO CHECK WIRING AND REFOCUS HEADLAMP		1 PC	20.00	
20 TO DISMANTLE AND REFIT AIRCON CONDENSER AND REFILL WITH AIR CON GAS		1 PC	100.00	
21 TO DISMANTLE AND REPLACE DAMAGE PARTS TO CUT, KNOCK AND WELD FRON SUPPORT PANEL KNOCK, ALIGN AND REPAIR FRONT AFFECTED AREA		1 PC	700.00	
22 TO SPRAY BONNET INNER / OUTER, FRONT FENDER LH, FRONT FENDER RH, FRONT BUMPER, FRONT DOOR LH, FRONT DOOR RH AND FRONT SUPPORT PANEL		1 PC	1,000.00	
				1,820.00

AH LIM MOTOR COMPANY
(SIN MING BRANCH)
176, Sin Ming Drive, #05-12
Sin Ming Autocare, Singapore 575721
Tel: 6456 3637 Fax: 6456 3686

AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : HL ASSURANCE PTE LTD
11 KEPPEL ROAD
#11-01 ABI PLAZA
SINGAPORE 089057
TEL: 67020202
ATTN: Motor Claim Department
Your Ref No: SLS1682H
Claim Type: Own Damage
Accident Date: 25/05/2023

Claim No: MCS1900907
Ref No: MFS1900821
Date: 25 Jul 2023
Policy No: MP314066
Veh Reg No: SLS1682H
Make/Model: TOYOTA HARRIER
Chassis No: ZSU600076537

Repair Cost to Vehicle No (For Finalization): SLS1682H

Amount Before Excess	S\$ 6,922.15
Less Excess	S\$ 375.00
Amount Before GST	S\$ 6,547.15
Add GST @ 8%	523.77
Total Amount payable	S\$ 7,070.92

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND SEVENTY AND CENTS NINETY TWO ONLY

The above vehicle was surveyed by KENETH KONG - LKK on 05/06/2023

For AH LIM MOTOR COMPANY


AH LIM MOTOR COMPANY
(SIN MING BRANCH)
AUTHORISED SIGNATURE #05-12
176, Sin Ming Drive, Singapore 575721
Sin Ming Autocare, Singapore 575721
Tel: 6456 3637 Fax: 6456 3686