

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**India International Insurance Pte Ltd  
6 Raffles Quay, #22-00  
Singapore 048580**Our File No:** CS/III23005467/KNY3E2**Date:** 28/06/2023REFERENCE

Insured/Claimant: GENERAL PIPING SERVICES AND SUPPLIES PTE LTD

Policy No: D22MFL0008943

Date of Loss: 20/05/2023

Nature of Claim: OD Claim No: MFL2023D0005927

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLT8052A**

Make &amp; Model: TOYOTA PRIUS, 1.8 (A)

Engine No: 2ZR8078645

Reg. Date: 13/11/2017 (Man. Year: 2017)

Chassis No: ZVW518036630

Colour: Metallic Black

Odometer: 166931 km

Engine Capacity: 1797 cc

Market Value/New Car Price: S\$75,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Farroad 8 mm

Rear Left Side: Firenza 6 mm

Front Right Side: Farroad 8 mm

Rear Right Side: Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>8,950.00</b>		
<b>- Excess (S\$)</b>	1,450.00	1,450.00	0.00	0.00
<b>(S\$)</b>	-1,450.00	7,500.00	-8,950.00	617.24
<b>+ GST 8.00/8.00% (S\$)</b>	0.00	600.00	-600.00	
<b>Nett Amount (S\$)</b>	<b>-1,450.00</b>	<b>8,100.00</b>	<b>-9,550.00</b>	<b>658.62</b>

INSPECTION

Date of Assignment: 30/05/2023

Date Inspected: 30/05/2023 Inspected At:

Ding Automotive Pte Ltd (SIN MING)  
BLK 10 #01-20 SIN MING, IND EST SEC C  
Singapore 575645

Estimated Period of Repair: 7.0 days

**Adjuster:** KENNETH KONG**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2023)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT8052A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >