Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: India International Insurance Pte Ltd

64 Cecil Street #04-00 IOB Building Singapore 049711 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Sherini Pillai Date: 31 May 2023

Preliminary Advice

Vehicle No: SLT8052AAccident Date: 20/05/2023Make: TOYOTA PRIUSPolicy No.: D22MFL0008943

Assignment Date : 30/05/2023 Excess : \$\$0.00 Date of Inspection : 30/05/2023 Est. Duration of Repair : 7

Inspection At : DING AUTO

Point of Impact / General Description of Damages

Parts claimed are not consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,434.50
Revised Amount	:S\$	6,806.50
Check Items (Estimated)	:S\$	5,630.00
Total	:S\$	12,436.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 75,000.00 COE / PARF Rebate :S\$ 25,320.00

Salvage Value :S\$

Margin for Repair :S\$ 49,680.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy cov	verage.
	Kindly let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.