

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Alfred Toh

Date: 09 Jun 2023

Preliminary Advice

Vehicle No	: SKR3462E	Accident Date	: 24/05/2023
Make	: AUDI A6	Policy No.	: DMPCSNW00026412300
Assignment Date	: 30/05/2023	Excess	: S\$0.00
Date of Inspection	: 08/06/2023	Est. Duration of Repair	: 10 DAYS
Inspection At	: WAH HONG MOTORS & CREDIT PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,336.20
Revised Amount	:S\$	8,081.20
Check Items (Estimated)	:S\$	3,995.00
Total	:S\$	12,076.20
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	52,000.00
COE / PARF Rebate	:S\$	35,098.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,902.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : LumpSum Repair.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour costs.