



ESTABLISHED 1984

# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGRG. &amp; MGT. DIVISION (TP)

Ref: CS3/SPF23005471/Kny3m4

ACCIDENT CLAIMS SECTION (SPORE POLICE  
FORCE) POLICE LOGISTICS BASE (PLB) 1  
HEMMANT ROAD SINGAPORE 438675

Date: 09/06/2023

ATTN: ENG CUI FEN

Code: SPF

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

<b>Insured Veh.</b>	QX 1215M	<b>Veh. Inspected</b>	SNA 5143S
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	ACS/105/009/2023/035	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ENG CUI FEN	<b>Assign Date</b>	29/05/2023

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HYUNDAI ELANTRA (A)	<b>c.c</b>	1591
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	KMHD841CMJU550387	<b>Colour</b>	M. P. WHITE
<b>Odometer</b>	164844 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/65R15	DUNLOP	9 mm
<b>L/H Front Tyre</b>	195/65R15	DUNLOP	9 mm
<b>R/H Rear Tyre</b>	195/65R15	DUNLOP	9 mm
<b>L/H Rear Tyre</b>	195/65R15	DUNLOP	9 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	10/05/2023	<b>Inspect Date / Time</b>	30/05/2023 ( 10:37 AM )
<b>Survey held at</b>	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:

**4 Working Days**