



1

of 2 ?

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD

Ref: CS3/HSB23005475/p3

10 MARINA BOULEVARD

Date: 30/05/2023

#48-01 MARINA BAY FINANCIAL CENTRE TOWER

2SINGAPORE 018983

Code: HSB

1. Policy Particulars :- (THIRD PARTY CLAIM)

| | | | |
|---------------------|-----------|-----------------------|------------|
| Insured Veh. | SHC 3040D | Veh. Inspected | SME 2945E |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | S3M04MV8 | Excess (\$) | 0.00 |
| Assign From | OH VALE | Assign Date | 30/05/2023 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|--------|---------------------|---|
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|-----------------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| | |
|--|--|
| | |
|--|--|

5. General Information

| | | | |
|-----------------------|--|------------------------|--|
| Accident Date | 25/05/2023 | Inspection Date | |
| Survey held at | YAP MOTOR REPAIR SERVICE BLK 7 SIN MING IND EST SEC C #01-80 & 82 SINGAPORE 575642 | | |

5a. Remarks

| | |
|--|--|
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |
|--|--|