

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/AG/123005477/UV43

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNA 4849X

at Workshop m/s 20m7t

of _____

Insured: SJU 80167

Policy No. _____

Claims No. C10022572/SR


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 46k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lump Sum: 22 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: L1A 824850

Veh No: SNA 4849X Yr Regn: 30/08/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Peugeot 308 SW c.c. 1199

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 128638 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF3LRHN/YWA 5050552

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55-16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 29/05/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & RL

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Rep 13k

7/6/23 Bel 3yrs 3mths Net 10,413.70 (red 10,413.70, 44%)
 4/5 & 13.100 in frame Roy

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 8

1)

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2) 7/6/23-typist

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : TP

Lump Sum / L.B.L. (\$ 13,100)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	857D
Vehicle Details	
Vehicle No.:	SNA4849X
Vehicle to be Exported:	No
Intended Deregistration Date:	30 May 2023
Vehicle Make:	PEUGEOT
Vehicle Model:	308 SW ALLURE PURETECH 1.2 A/T 2WD S/R
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	10XT180266415
Chassis No.:	VF3LRHNYWGS050552
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,133.00
Original Registration Date:	30 Aug 2016
First Registration Date:	30 Aug 2016
Transfer Count:	1
Actual ARF Paid:	\$11,587.00 5793
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2026
PARF Rebate Amount:	\$7,531.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,334.00
COE Rebate Amount:	\$17,319.00
Total Rebate Amount:	\$24,850.00

The information contained herein is correct as at 30 May 2023

OK

Car Accessories & Products

Pimping up your ride? Browse thousands of car products for even more choices!
Read honest reviews by our trusted consumers before you make a purchase.

Post an Advertisement

Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Low Interest Rate In-House Loan by GV Cars Financing



\$0 Downpayment. 90% Loan by
GV Cars Financing at 3.28% p.a.
Low Interest Rate.
GV Automobile Centre StarAd

PRIME MOTOR
ICHENG YONG CREDIT ENTERPRISES PTE
With over 200 units of vehicle
to choose from, ranging from
all European to Japanese Make

Sort by [Date Posted](#)


8 vehicles



PEUGEOT 308

Any Category

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh
Search Selection	PEUGEOT 308		Any	Any	2016	Any	Any	
	Peugeot	308 SW 1.2A PureTech Allure Glass Roof	\$55,800	\$14,300 /yr	24-Nov-2016	1,199 cc	93,600 km	Stationary
Highly practical family stationwagon paired with decent price tag! High Spec With Glass Roof. Very Fuel Economical! Spacious cabin and...								
Posted: 29-May-2023								
	Peugeot	308 1.2A PureTech Allure	\$49,900	\$13,620 /yr	06-Oct-2016	1,199 cc	75,800 km	Hatchback
Sporty Black Peugeot Hatchback, Serviced and Maintained by Agent, This is Not a Rental/Limousine Unit. Genuine Low Mileage Done, Ve...								
Prime Motor & Leasing								
Posted: 29-May-2023								
	Peugeot	308 SW 1.2A PureTech Allure	\$53,058	\$13,430 /yr	30-Dec-2016	1,199 cc	83,000 km	Stationary
Lowest interest rate per annum! Full loan available! Hassle free! Fast approvals, accident free, 1year warranty, with servicing record! Und...								
Apex Automotive Services Pte Ltd								
Posted: 27-May-2023								
	Peugeot	308 1.2A PureTech Allure	\$39,800	\$12,800 /yr	26-Feb-2016	1,199 cc	89,351 km	Hatchback
Full loan with 100% approval rate! Well maintained by previous owner. 6 months 1 free servicing by reputable workshop with 25 years e...								
Posted: 27-May-2023								
	Peugeot	308 1.2A PureTech Allure Glass Roof (OPC)	\$38,888	\$12,000 /yr	26-Feb-2016	1,199 cc	35,664 km	Hatchback
The Peugeot 308 is the perfect car for those who demand style and performance. With its sleek exterior design, innovative technology, a...								
Carro								
Posted: 23 May-2023								

[Compare](#)

Prompt Auto Solutions Pte Ltd

8 Kaki Bukit Avenue 4 #02-37 @ Kaki Bukit (415875)

Tel: 97319322 - ROY CHAK

E-mail: promptautosolutions@gmail.com

NOT AUTHORIZED
MARUSHA
30/5/23

L/S \$13,100

who photo the repair

8 days

REPAIR ESTIMATE

TO :	DATE :
ATTENTION :	JOB TYPE : THIRD PARTY
VEHICLE DETAILS	
VEHICLE NO: SNA4849X	ACCIDENT DETAILS
MAKE / MODEL: Peugeot 308	DATE :
CHASSIS NO: VF3LRHNYWGS050552	TIME :

S/N	DESCRIPTIONS	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	Tailgate 1812	1	warped (one)	\$ 1,856.00
2	Tailgate "Peugeot" emblem	1	new	\$ 82.00
3	Tailgate centre emblem	1	new	\$ 101.00
4	Tailgate "308" emblem	1	new	\$ 49.00
5	Tailgate weatherstrip 182	1	new	\$ 211.00
6	Tailgate lock	1	daye	\$ 187.00
7	Tailgate lock catch	1	new	\$ 47.00
8	Tailgate inner trim board	1	de/turn	\$ 505.00
9	Tailgate inner trim board clips	1set	new	\$ 50.00
10	Tailgate RH lamp	1	scr	\$ 466.00
11	Tailgate LH lamp	1	scr	\$ 466.00
12	Tailgate RH number plate lamp	1	new	\$ 86.00
13	Tailgate LH number plate lamp	1	new	\$ 86.00
14	Rear bumper 1215	1	De J	\$ 1,492.00
15	Rear bumper lower diffuser	1	De J	\$ 458.00
16	Rear bumper tow cover	1	to-1	\$ 22.00
17	Rear bumper clips	1set	new	\$ 50.00
18	Rear bumper RH reflector	1	new	\$ 94.00
19	Rear bumper LH reflector	1	new	\$ 94.00
20	Rear bumper reverse sensors 175x3 = 525	4	malfunction	\$ 764.00
21	Rear bumper reverse sensor holders	4	new	\$ 88.00
22	Rear bumper RH side retainer	1	new	\$ 67.00
23	Rear bumper LH side retainer	1	new	\$ 67.00
24	Rear bumper centre bracket	1	new	\$ 91.00
25	Rear bumper reinforcement	1	best	\$ 472.00
26	End panel	1	best	\$ 674.00
27	End panel inner garnish	1	new	\$ 178.00
28	RH taillamp	1	new	\$ 591.00
29	LH taillamp	1	new	\$ 591.00
30	Exhaust silencer	1	new	\$ 973.00
31	Exhaust silencer gaslet	1	new	\$ 42.00
32	Bonnet	1	new	\$ 1,364.00
33	Bonnet emblem	1	new	\$ 112.00
34	Bonnet inner shield	1	new	\$ 276.00
35	Bonnet inner shield clips	1set	new	\$ 60.00
36	Front bumper	1	de/turn	\$ 1,132.00
37	Front bumper sensors 175	4	malfunction	\$ 764.00
38	Front bumper sensor holder	4	new	\$ 88.00
39	Front bumper lower grille	1	new	\$ 203.00
40	Front bumper clips 50	1set	new	\$ 60.00
41	Front bumper RH retainer	1	new	\$ 67.00
42	Front bumper LH retainer	1	new	\$ 67.00
43	Front bumper reinforcement	1	best	\$ 482.00
44	Front bumper inner sponge	1	to-1	\$ 167.00
45	Front chrome grille	1	scr/one	\$ 404.00
46	RH headlamp	1	holder new	\$ 1,583.00
47	LH headlamp	1	holder new	\$ 1,583.00
48	Aircon condenser	1	new	\$ 1,031.00
	Rear floor panel tails sponge 520 turn			

100

TOTAL PRICE: \$ 20,393.00

SUB TOTAL PRICE: \$ 18,353.70

S/N	DESCRIPTIONS	QTY	UNIT S/N PRICE	TOTAL S/N PRICE
1	Tailgate glass sealant	1	70.00	70.00
2	Tailgate glass inner sealant	1	50.00	50.00
3	Rear number plate	1	70.00	70.00
4	Front number plate	1	70.00	70.00

S/N TOTAL PRICE: \$ 260.00

S/N	DESCRIPTIONS	PRICE
1	Labour charges on affected areas and replaced parts as listed	1,500.00
2	Re-spray affected areas and parts	1,500.00
3	Check wiring and lighting system	100.00
4	Apply anti rust chemical coating	80.00
5	Remove and replace aircon condenser and refill gas	260.00
6	Remove and replace front bumper sensors and holders	120.00
7	Remove and refit tailgate glass and replace sealants	180.00
8	Remove and replace tailgate inner parts to new tailgate	120.00
9	Remove and replace rear bumper reverse sensors and holders	120.00
10	Remove and replace end panel inner garnish and trims	220.00
11	Remove and replace exhaust silencer and gasket	180.00

LABOUR TOTAL PRICE: \$ 4,380.00

ESTIMATE REPORT

TOTAL PARTS PRICE : \$ 18,613.70
TOTAL LABOUR PRICE : \$ 4,380.00
TOTAL AMOUNT : \$ 22,993.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P 14965
102
13468.50
120
2840
16428.50
202
13142