

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SML7735A

Make & Model: Honda Shuttle

Chassis number: GP72008560

No.	Description of spare parts	Qty	Amount S\$
1	Tailgate	1	\$ <i>ht</i> 1,272.00
2	Tailgate windscreen glass rubber moulding	1	\$ <i>wt</i> 155.00
3	Tailgate windscreen glass	1	\$ <i>br</i> 1,268.00
4	Tailgate centre emblem	1	\$ <i>wy</i> 46.00
5	Tailgate chrome moulding garnish	1	\$ <i>org</i> 331.00
6	Tailgate chrome moulding garnish clips	1set	\$ <i>wt</i> 80.00
7	Tailgate "Shuttle" emblem	1	\$ <i>wt</i> 58.00
8	Tailgate RH lamp assy	1	\$ <i>aw</i> 443.00
9	Tailgate RH lamp gasket	1	\$ <i>x</i> 25.00
10	Tailgate LH lamp assy	1	\$ <i>aut</i> 443.00
11	Tailgate LH lamp gasket	1	\$ <i>x</i> 25.00
12	Tailgate RH number plate lamp	1	\$ <i>x</i> 35.00
13	Tailgate LH number plate lamp	1	\$ <i>x</i> 35.00
14	Tailgate lock	1	\$ <i>ht</i> 191.00
15	Tailgate lock catch	1	\$ <i>x</i> 45.00
16	Tailgate inner trim board	1	\$ <i>de</i> 354.00
17	Tailgate inner trim board clips	1set	\$ <i>wt</i> - 20 60.00
18	Tailgate inner RH side garnish	1	\$ <i>x</i> 93.00
19	Tailgate inner RH side garnish clips	1set	\$ <i>x</i> 40.00
20	Tailgate inner LH side garnish	1	\$ <i>x</i> 93.00
21	Tailgate inner LH side garnish clips	1set	\$ <i>fix</i> 40.00
22	Tailgate weatherstrip	1	\$ <i>wt</i> 189.00
23	Tailgate pull handle	1	\$ <i>de</i> 32.00
24	Tailgate RH damper	1	\$ <i>x</i> 223.00
25	Tailgate LH damper	1	\$ <i>x</i> 223.00
26	Tailgate RH hinge	1	\$ <i>x</i> 98.00
27	Tailgate LH hinge	1	\$ <i>x</i> 98.00
28	Tailgate wiper motor	1	\$ <i>x</i> 683.00
29	Tailgate wiper arm inner seal	1	\$ <i>x</i> 15.00
30	Tailgate wiper arm	1	\$ <i>x</i> 148.00
31	Tailgate wiper blade	1	\$ <i>x</i> 83.00
32	Tailgate spoiler	1	\$ <i>x</i> 948.00
33	Rear bumper	1	\$ <i>de</i> 1,153.00
34	Rear bumper clips	1set	\$ <i>wt</i> - 30 80.00
35	Rear bumper towing cover	1	\$ <i>ds</i> 32.00

36	Rear bumper RH reflector	1	\$ <i>sub</i> 64.00
37	Rear bumper RH reflector garnish	1	\$ <i>de</i> 58.00
38	Rear bumper RH inner sponge	1	\$ <i>cur</i> 98.00
39	Rear bumper LH reflector	1	\$ <i>x</i> 64.00
40	Rear bumper LH reflector garnish	1	\$ <i>x</i> 58.00
41	Rear bumper LH inner sponge	1	\$ <i>x</i> 98.00
42	Rear bumper RH side retainer	1	\$ <i>de</i> 42.00
43	Rear bumper LH side retainer	1	\$ <i>x</i> 42.00
44	Rear bumper RH bracket	1	\$ <i>de</i> 57.00
45	Rear bumper LH bracket	1	\$ <i>x</i> 57.00
46	Rear bumper RH lower cover	1	\$ <i>x</i> 112.00
47	Rear bumper LH lower cover	1	\$ <i>x</i> 112.00
48	End panel (outer)	1	\$ <i>bt</i> 567.00
49	End panel (inner)	1	\$ <i>bt</i> 487.00
50	End panel buzzer sensor	1	\$ <i>x</i> 98.00
51	End panel antenna sensor	1	\$ <i>x</i> 98.00
52	RH taillamp assy	1	\$ <i>cur</i> 558.00
53	RH taillamp gasket	1	\$ <i>re</i> 28.00
54	RH taillamp lock clips	1	\$ <i>x</i> 44.00
55	RH taillamp panel	1	\$ <i>buy</i> 142.00
56	LH taillamp assy	1	\$ <i>sub</i> 558.00
57	LH taillamp gasket	1	\$ <i>x</i> 28.00
58	LH taillamp lock clips	1	\$ <i>x</i> 44.00
59	LH taillamp panel	1	\$ <i>x</i> 142.00
60	Roof lining	1	\$ <i>de</i> 1,256.00
61	Roof lining clips	1set	\$ <i>wt</i> 30 85.00
62	Rear RH fender	1	\$ <i>buy</i> 1,010.00
63	Rear RH fender inner panel	1	\$ <i>Rp</i> 849.00
64	Rear RH fender glass with rubber moulding	1	\$ <i>cur</i> 578.00
65	Rear RH fender inner trim board	1	\$ <i>cur</i> 505.00
66	Rear RH fender inner trim board clips	1set	\$ <i>30w</i> 80.00
67	Rear RH fender inner upper board	1	\$ <i>de</i> 382.00
68	Rear RH fender inner upper board clips	1set	\$ <i>30w</i> 60.00
69	Rear RH fender splash shield	1	\$ <i>fr</i> 73.00
70	Rear RH fender splash shield clips	1set	\$ <i>20w</i> 50.00
71	Rear LH fender inner trim board	1	\$ <i>buy</i> 505.00
72	Rear LH fender inner trim board clips	1set	\$ <i>x</i> 80.00
73	Rear LH fender splash shield	1	\$ <i>x</i> 73.00
74	Rear LH fender splash shield clips	1set	\$ <i>x</i> 50.00
75	Rear compartment panel	1	\$ <i>buy</i> 1,180.00
76	Rear compartment panel tray box	1	\$ <i>de</i> 448.00
77	Rear compartment tray box cover	1	\$ <i>de</i> 321.00
78	Rear compartment foldable top cover	1	\$ <i>x</i> 655.00
79	Rear compartment inner sponge	1	\$ <i>cur</i> 489.00
80	Rear compartment top cover board	1	\$ <i>x</i> 585.00
81	Exhaust silencer	1	\$ <i>x</i> 756.00
82	Exhaust silencer gasket	1	\$ <i>x</i> 42.00
83	Third row seat RH seat belt	1	\$ <i>x</i> 589.00

84	Rear RH door	1	\$ x <i>Ry</i>	836.00
85	Rear RH door frame black sticker	1	\$ x	39.00
86	Rear RH door lock	1	\$ x	211.00
87	Rear RH door inner trim board	1	\$ x	497.00
88	Rear RH door inner trim board clips	1set	\$ x	70.00
89	Front RH door weatherstrip	1	\$ x	78.00
90	RH side rocker panel garnish	1	\$ x	398.00
91	RH side rocker panel garnish clips	1set	\$ x	80.00
92	Rear axle beam	1	\$ x	2,371.00
93	Rear RH wheel bearing	1	\$ x	321.00
94	Rear RH shock absorber	1	\$ x	298.00
95	Rear LH wheel bearing	1	\$ x	321.00
96	Rear LH shock absorber	1	\$ x	298.00
97	Front bumper	1	\$ x	1,051.00
98	Front bumper clips	1set	\$ x	80.00
99	Front bumper LH side retainer	1	\$ x	22.00
100	LH headlamp assy	1	\$ x	2,250.00
101	LH headlamp lower bracket	1	\$ x	48.00
102	Front LH fender	1	\$ x	371.00
103	Front LH fender splash shield	1	\$ x	131.00
104	Front LH fender splash shield clips	1set	\$ x	50.00
105	Front LH fender glass rubber moulding	1	\$ x	52.00
106	Front LH shock absorber	1	\$ x	482.00
107	Front LH lower arm	1	\$ x ?	289.00
108	Front LH kunckle arm	1	\$ x ?	334.00
109	Front LH wheel bearing	1	\$ x ?	171.00
110	Front LH tie rod end	1	\$ x	83.00
111	Front LH drive shaft	1	\$ x	1,021.00
112	Steering rack and pinion	1	\$ x	1,189.00
113	LH side rocker panel garnish	1	\$ x	398.00
114	LH side rocker panel garnish clips	1set	\$ x	80.00

\$ 37,414.00
 Parts less 20% \$ 7,482.80
 Total: \$ 29,931.20

No.	Special Nett Items	Qty	Amount S\$
1	Rear number plate	1	\$ x 80.00
2	Tailgate windscreen glass sealant	1	\$ <i>4me</i> 80.00
3	Tailgate windscreen glass inner seal	1	\$ <i>3me</i> 60.00
4	Tailgate windscreen glass solar flim	1	\$ x 380.00
5	Tailgate reverse camera	1	\$ x 750.00
6	Rear bumper reverse sensor	1set	\$ <i>200</i> 350.00

nm

7	Rear RH door sun visor	1	\$ X	280.00
8	Rear RH fender glass sealant	1	\$ <i>neg</i>	80.00
9	Rear RH fender glass inner seal	1	\$ X	60.00
10	Rear RH fender glass solar flim	1	\$ X	300.00
11	Rear RH fender joint sealant	1	\$ <i>50w</i>	80.00
12	Rear RH fender inner panel joint sealant	1	\$ X	85.00
13	End panel (outer) joint sealant	1	\$ <i>75w</i>	60.00
14	End panel (inner) joint sealant	1	\$ <i>50w</i>	60.00
15	LH taillamp panel joint sealant	1	\$ X	40.00
16	RH taillamp panel joint sealant	1	\$ <i>20w</i>	40.00
17	Rear compartment panel joint sealant	1	\$ <i>40w</i>	90.00
18	Brake fluid	1	\$ X	90.00
19	Rear RH sport rim	1	\$ X	950.00
20	Rear RH tyre	1	\$ X	550.00
21	Rear LH sport rim	1	\$ X	950.00
22	Rear LH tyre	1	\$ X	550.00
23	Front LH sport rim	1	\$ <i>dd</i>	950.00 <i>800</i>
24	Front LH tyre	1	\$ <i>painted</i>	550.00 <i>200</i>
				<i>80%</i>
Total:			\$	7,465.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ <i>1400</i> 3,000.00
2	Spray painting on affected areas and panels	\$ <i>1500</i> 2,600.00
3	Check wiring and lighting system on affected areas	\$ <i>40</i> 120.00
4	Apply rust coating chemical on affected areas and panels	\$ <i>60</i> 180.00
5	Replace and realign tailgate windscreen glass and sealants	\$ <i>120</i> 220.00
6	Remove and replace tailgate reverse camera to assist repair	\$ <i>30</i> 100.00
7	Remove and replace tailgate inner mechansim to new tailgate	\$ <i>60</i> 150.00
8	Remove and replace roof lining, seats and carpet to assist repair	\$ <i>100</i> 480.00
9	Remove and replace rear bumper reverse sensors to assist repair	\$ <i>40</i> 100.00

10	Test drive and adjust wheel alignment system	\$ 80. 180.00
11	Remove and replace rear undercarriage parts to assist repair	\$ X 550.00
12	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 60 350.00
13	Remove and replace exhaust silencer and gasket to assist repair	\$ X 180.00
14	Replace and realign rear RH fender glass and sealants to assist repair	\$ 60 200.00
15	Remove and replace rear RH door inner mechanism to new door	\$ X 150.00
16	Remove and replace front undercarriage parts to assist repair <i>front</i>	\$ 150 400.00
17	Refocus and adjust headlamps assy	\$ X 50.00
18	Remove and replace rear seat belts to assist repair	\$ X 220.00
19	Conduct diagnostic and reset system	\$ X 450.00
		Total: \$ 6,680.00

Agreed Amount: _____ (Part by Part / Lump sum)
Working days: _____

Spare Parts: \$ 29,931.20
Special Nett: \$ 7,465.00
Labour: \$ 6,680.00

Total Amount: \$ 44,076.20

Tanjiun 97495749
Wp 30/5/22 @ 345pm

CLs Resurvey after repair

Tanjiun @ Wharfedale

- To check consistency of accident
 - To check part prices
- 10-12 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date of Accident : 27/05/2023 . Accident Time: 0557 . (24-HR-FORMAT)
Accident Place : Changi South Ave 3 .
Vehicle Reg. No (Car plate No.) : SML7735A . CC: 1500 . Vehicle Make/Model: Honda Shuttle .
Insurance Company : Allianz . Policy No. 872002547365 .
Name of Registered Owner : Company / Individual PW 1012 Pk Htl.
ID of Registered Owner : Co Reg No: 20221004M . Owner's NRIC No: _____
OWNER EMAIL ADDRESS: reporting.gt@gmail.com : Co Contact No: 8855 6141 . Owner's Contact No: _____
DRIVER'S Name : Rohaizan Bin Hatnin . DRIVER'S NRIC No: 87523437F .
DRIVER'S Date of Birth : 20/07/1975 . DRIVER'S License Pass Date 23/10/2002 .
Relationship bet. Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: Wife .
DRIVER'S Address : 17, Teck Whye Lane . #08-163, S(680017) .
DRIVER'S Contact No./ Alt No. : 1) 89268675 . 2) _____
DRIVER'S Occupation : INDOOR \ OUTDOOR (eg. working inside or outside of an ofc)
Email Address : rbh200775@gmail.com .
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Offer Party \ Claim Own Insurance
Number of Passengers (including Driver): 1 . Name & Gender: _____
Was the accident reported to the police? YES \ NO
Was there any video Captured by car camera: YES \ NO
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work Purpose
Any injuries, if yes(name of the injured person) Rohaizan Bin Hatnin .

Other Party Driver's Particulars (if any)

Vehicle Reg No: <u>PC 5356K</u> .	Vehicle Reg No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name DRIVER: _____	Name DRIVER: _____
IC No. DRIVER: _____	IC No. DRIVER: _____
DRIVER'S Contact & add: _____	DRIVER'S Contact & add: _____

REPORT FORM EXPLAINED IN : ENGLISH / CHINESE / MALAY / TAMIL OTHERS: _____

WHO REPORTED THE ACCIDENT : OWNER / DRIVER / BOTH

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for Investigation.**
6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan




扫描全能王 创建

Describe Circumstance of the Accident

On the stated date and time, I was travelling along Changi South Ave 3. When my vehicle ran into some error. I then pulled over to the side of the road with my hazard lights on while I contact my workshop for assistance. All of a sudden in less than 2 minutes after stopping, I felt a huge impact from the rear of my vehicle. The impact was so huge that it pushed my car up the kerb and back onto the road. When I got off my vehicle, I then realised vehicle B had collided onto my rear.

Declaration

I/We declare the foregoing particulars are true in every respect.



Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

004M

Vehicle Details

Vehicle No.:

SML7735A

Vehicle to be Exported:

Yes

Intended Deregistration Date:

29 May 2023

Vehicle Make:

HONDA

Vehicle Model:

SHUTTLE HYBRID 1.5 AUTO

Primary Colour:

Red

Manufacturing Year:

2019

Engine No.:

LEB7110703

Chassis No.:

GP72008560

Maximum Power Output:

101.0 kW (135 bhp)

Open Market Value:

\$21,760.00

Original Registration Date:

03 Jun 2019

First Registration Date:

03 Jun 2019

Transfer Count:

1

Actual ARF Paid:

\$12,464.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

02 Jun 2029

PARF Rebate Amount:

\$9,348.00

Intended COE Rebate Details

COE Expiry Date:

02 Jun 2029

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$42,564.00

COE Rebate Amount:

\$25,584.00

Total Rebate Amount:

\$34,932.00

The information contained herein is correct as at 29 May 2023

OK