

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : **SNH 1326X**

Made : Mazda

Model : Mazda 3 M-Hybrid

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper	1	\$ 867.30	\$ <i>fn</i> 867.30
2	Front Bumper Side Retainer RH	1	\$ 19.70	\$ <i>de</i> 19.70
3	Front Bumper Side Retainer LH	1	\$ 19.70	\$ <i>X</i> 19.70
4	Front Bumper Bracket RH	1	\$ 15.90	\$ <i>X</i> 15.90
5	Front Bumper Bracket LH	1	\$ 15.90	\$ <i>X</i> 15.90
6	Front Bumper Tow Cover RH	1	\$ 18.20	\$ <i>X</i> 18.20
7	Front Bumper Clips	10	\$ 3.70	\$ <i>230.10</i> 37.00
8	Front Bumper Fastener	2	\$ 3.00	\$ <i>X</i> 6.00
9	Front Bumper Fog Lamp Cover RH	1	\$ 30.50	\$ <i>X</i> 30.50
10	Front Bumper Reinforcement	1	\$ 502.80	\$ <i>X</i> 502.80
11	Front Bumper Reinforcement Garnish	1	\$ 92.70	\$ <i>X</i> 92.70
12	Front Bumper Top Garnish	1	\$ 358.10	\$ <i>X</i> 358.10
13	Front Bumper Lower Grille	1	\$ 268.20	\$ <i>X</i> 268.20
14	Front Bumper Number Plate Garnish	1	\$ 79.30	\$ <i>X</i> 79.30
15	Front Grille Assembly	1	\$ 610.70	\$ <i>cur</i> 610.70
16	Front Grille Emblem	1	\$ 108.50	\$ <i>net</i> 108.50
17	Front Grille Chrome Moulding RH	1	\$ 298.20	\$ <i>cur</i> 298.20
18	Front Grille Chrome Moulding LH	1	\$ 298.20	\$ <i>X</i> 298.20
19	Front Grille Bracket RH	1	\$ 15.90	\$ <i>X</i> 15.90
20	Front Grille Bracket LH	1	\$ 15.90	\$ <i>X</i> 15.90
21	Front Grille Rivets	2	\$ 8.00	\$ <i>net</i> 16.00
22	Front Headlamp Assembly RH	1	\$ 2,267.80	\$ <i>net</i> 2,267.80
23	Front Headlamp Bracket RH	1	\$ 56.20	\$ <i>cur</i> 56.20
24	Front Headlamp Assembly LH	1	\$ 2,267.80	\$ <i>X</i> 2,267.80
25	Front Headlamp Bracket LH	1	\$ 56.20	\$ <i>X</i> 56.20
26	Front Support Panel	1	\$ 493.20	\$ <i>X</i> 493.20
27	Radiator Air Deflector RH	1	\$ 149.50	\$ <i>gra</i> 149.50
28	Radiator Air Deflector LH	1	\$ 149.50	\$ <i>X</i> 149.50
29	Front Bonnet	1	\$ 1,040.80	\$ <i>X</i> 1,040.80
30	Front Bonnet Weatherstrip	1	\$ 66.80	\$ <i>X</i> 66.80
31	Front Bonnet Lock	1	\$ 189.30	\$ <i>X</i> 189.30
32	Front Bonnet Hinge RH	1	\$ 76.60	\$ <i>X</i> 76.60

33	Front Bonnet Hinge LH	1	\$	76.60	\$ X	76.60
34	Front Bonnet Insulator	1	\$	172.00	\$ X	172.00
35	Front Bonnet Insulator Clips	10	\$	2.70	\$ X	27.00
36	Front Fender RH	1	\$	413.20	\$ <i>bt</i>	413.20
37	Front Fender Stay RH	1	\$	41.90	\$ X	41.90
38	Front Fender Inner Shield RH	1	\$	101.90	\$ <i>mi</i>	101.90
39	Front Fender Inner Shield Clips RH	16	\$	3.00	\$ 20.00 X	48.00
40	Aircon Condenser	1	\$	982.60	\$ X	982.60
41	Radiator	1	\$	1,082.60	\$ X	1,082.60
42	Radiator Fan Cowling with Fan Motor	1	\$	1,496.90	\$ X	1,496.90
43	Front Wheel Rim RH	1	\$	1,053.58	\$ <i>cut</i>	1,053.58
44	Front Shock Absorber RH	1	\$	345.74	\$ X	345.74
45	Front Lower Arm RH	1	\$	520.89	\$ X	520.89
46	Front Knuckle Arm RH	1	\$	432.81	\$ X	432.81
47	Front Knuckle Arm Bearing RH	1	\$	201.00	\$ X	201.00
48	Front Door Side Mirror Assembly RH	1	\$	659.20	\$ X	659.20
49	Front Door Side Mirror Cover RH	1	\$	75.30	\$ X	75.30
50	Front Door Side Mirror Signal Lamp RH	1	\$	124.30	\$ X	124.30
51	Front Door RH	1	\$	1,326.50	\$ X	1,326.50
52	Front Door Upper Hinge RH	1	\$	60.00	\$ X	60.00
53	Front Door Lower Hinge RH	1	\$	60.00	\$ X	60.00
54	Front Door Inner Lock RH	1	\$	278.00	\$ X	278.00
55	Front Door Outer Glass Chrome Moulding RH	1	\$	160.90	\$ X	160.90
56	Front Door Moulding Upper RH	1	\$	145.00	\$ X	145.00
57	Front Door Weatherstrip RH	1	\$	182.00	\$ X	182.00
58	Rocker Panel RH	1	\$	898.00	\$ X	898.00

Parts Sub Total : \$ 21,474.32

20% Discount \$ 4,294.86

PARTS TOTAL : \$ 17,179.46

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate	1	\$ 50.00	\$ X 50.00
2	Front Bumper Clips - Set	1	\$ 50.00	\$ <i>50 Zone</i> 50.00
3	Front Grille Clips - Set	1	\$ 50.00	\$ X 50.00
4	Front Bonnet Insulator Clips - Set	1	\$ 50.00	\$ X 50.00
5	Front Fender Inner Shield RH Clips - Set	1	\$ 50.00	\$ <i>Zone</i> 50.00
6	Front Door Inner Trim Board RH Clips - Set	1	\$ 50.00	\$ X 50.00
7	Front Bonnet Sealant	1	\$ 150.00	\$ X 150.00
8	Front Fender RH Sealant	1	\$ 150.00	\$ X 150.00
9	Front Door RH Sealant	1	\$ 150.00	\$ X 150.00
10	Rocker Panel RH Sealant	1	\$ 150.00	\$ X 150.00
11	Radiator Coolant	1	\$ 60.00	\$ X 60.00
12	Front Tyre RH	1	\$ 350.00	\$ X 350.00
SPECIAL NETT TOTAL :				\$ 1,310.00

Nos.	LABOUR	S\$
1	To Panel Beat, Remove & Refix Parts	\$ 400 1,800.00
2	To Spray Paint Affected Areas	\$ 450 1,400.00
3	Wiring & Bulb Check	\$ 30 100.00
4	To Transfer Front Door RH Mechanism	\$ X 150.00
5	To Remove & Refix Aircon Condenser and Top Up Gas	\$ X 150.00
6	To Remove & Refix Radiator and Pressure Test	\$ X 150.00
7	To Remove & Refix Front Undercarriage	\$ X 450.00
8	To Remove & Refix Front Tyre and Conduct Wheel Balancing	\$ 30 150.00
9	To Conduct Four Wheel Alignment	\$ 80 150.00
10	To apply anti rust on affected parts	\$ 30 120.00
11	To Conduct Water Leak Test	\$ X 100.00
12	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X 480.00
LABOUR TOTAL :		\$ 5,200.00

PARTS TOTAL : \$ 17,179.46

SPECIAL NETT TOTAL : \$ 1,310.00

LABOUR TOTAL : \$ 5,200.00

GRAND TOTAL : \$ 23,689.46

Tanflin 97495719

WP' 21/5/23 @ 230 pm

4/5 Resurvey after repair

Tanflin @ Lkh auto. wh

- To check consistency of accident
- To check part prices

3-4 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: