

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0467/2023/EQ
DATE : 15-May-23
WIP : 20814

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/5/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS MALATHI D/O MUTHU VERAN
ADDRESS : BLK 410 BEDOK NORTH AVENUE 2
#07-76
SINGAPORE 460410
TELEPHONE : HP +65 92205688
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800109793-03
VEHICLE NO : **SME 177 T**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 14/9/2018
ENGINE NO : CVK 068599
CHASSIS NO : WAUZZZF53JA134014
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-May-23
PLACE OF ACCIDENT : BENOI ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SME 177 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO RENEW 1/4 GLASS TO FACILLITATE REAR FENDER RENEWAL.	S/N \$	300.00	✓
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS.	S/N \$	400.00	✓
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	✓
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	✓
6	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	280 ✓
TOTAL LABOUR CHARGES		:	\$	4,660.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SME 177 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. CUT OUT AND WELD TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,200.00	3000.
8	TO RESPRAY REAR BUMPER, RHS REAR FENDER, END PANELLING, RHS REAR DOOR, RHS SILL PANEL TRIM, RHS SILL PANEL, ROOF CHANNEL, DOOR HANDLE, DRAIN CHANNEL AND DOOR ENTRANCES.	\$ 7,500.00	5.5 x 550 = 3025
9	TO RENEW RHS REAR RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	280.
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 20,072.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SME 177 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>At</i>	1	\$ 3,187.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 289.00	?
3	REAR BUMPER SECURING STRIP <i>?</i>	1	\$ 264.00	?
4	REAR BUMPER CHROME TRIM <i>?</i>	1	\$ 1,206.00	?
5	REAR BUMPER GUIDE SECTION - RH UPPER <i>new</i>	1	\$ 27.00	X
6	REAR BUMPER GUIDE SECTION - RH <i>new</i>	1	\$ 52.00	X
7	REAR SIDE PANEL - RH <i>Dented</i>	1	\$ 4,315.00	✓
8	REAR QUARTER WINDOW - RH <i>new</i>	1	\$ 844.00	✓
9	WINDOW PRIMER <i>new</i>	1	\$ 24.00	✓
10	REAR FUEL INSERT <i>new</i>	1	\$ 106.00	X.
11	REAR WHEEL HOUSING LINER - RH <i>new</i>	1	\$ 322.00	X
12	ATTACHMENT PARTS <i>new</i>	1	\$ 144.00	X
13	ADHESIVE TAPES <i>new</i>	1	\$ 230.00	X.
14	REAR DOOR - RH <i>Repair</i>	1	\$ 4,210.00	X
15	REAR DOOR OUTER SEAL - RH <i>new</i>	1	\$ 261.00	X
16	BONDING AGENT <i>new</i>	1	\$ 51.00	X
17	CLEANING SOLUTION <i>new</i>	1	\$ 80.00	X
18	APPLICATOR	1	\$ 9.00	X
19	REAR DOOR CATCH - RH <i>new</i>	1	\$ 141.00	X
20	REAR DOOR HANDLE TRIM PLATE - RH <i>At</i>	1	\$ 149.00	✓
SUB TOTAL SPARE PARTS			\$ 15,911.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SME 177 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR HANDLE CHROME TRIM - RH <i>new</i>	1	\$ 161.00	✓
22	REAR DOOR HANDLE COVER - RH <i>?</i>	1	\$ 8.00	?
23	REAR DOOR HANDLE HOUSING - RH <i>?</i>	1	\$ 11.00	?
24	REAR ALUMINIUM RIM - RH <i>cut</i>	1	\$ 2,000.00	✓
25	REAR ALUMINIUM RIM RUBBER VALVE <i>new</i>	1	\$ 4.00	X
26	ACRYLIC SEALANT <i>?</i>	S/N	\$ 180.00	✓
27	CAVITY WAX	S/N	\$ 140.00	✓
28	METAL FILLER POWDER <i>new</i>	S/N	\$ 280.00	✓
29	STONE CHIP	S/N	\$ 180.00	✓
30	1/4 GLASS SEALANT	S/N	\$ 100.00	✓
31	SUNDRIES <i>?</i>		\$ 600.00	?
TOTAL SPARE PARTS		:	\$ 19,575.00	
TOTAL LABOUR CHARGES		:	\$ 20,072.00	
GRAND TOTAL		:	\$ 39,647.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *16/05/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 14 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT