



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23005488/Uny3e2	
			Date: 09/06/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMC 1954X	Veh. Inspected	SNJ 614K
	Policy No.	D23MTRENT000227	Coverage (\$)	0.00
	Claim No.	CMTD2302173/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	30/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA COROLLA CROSS HYBRID (A)	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	ZVG111007401	Colour	BLUE
	Odometer	17615 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R17	BRIDGESTONE	7 mm
	L/H Front Tyre	215/60 R17	BRIDGESTONE	7 mm
	R/H Rear Tyre	215/60 R17	BRIDGESTONE	7 mm
	L/H Rear Tyre	215/60 R17	BRIDGESTONE	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/05/2023	Inspection Date	31/05/2023
	Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	