

Date: 30/05/2023
Vehicle No: SNH156B
Model: MERCEDES BENZ A200 HATCHBACK
Chassis: W1K1770872N159493-2020
Reg.Year: 2022

Third Party Insurer: LONPAC
Third Party Veh No: YQ6759U
Date of Accident: 29/05/2023
Estimator: TING AN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		\$2,580.00
2	REAR TAILGATE "A200" EMBLEM	1		\$138.00
3	REAR TAILGATE "MERCEDES" EMBLEM	1		\$66.00
4	REAR TAILGATE INNER LOCK	1		\$328.00
5	REAR TAILGATE INNER TRIM BOARD	1		\$220.00
6	REAR TAILGATE WEATHERSTRIP	1		\$351.00
7	REAR TAILGATE LAMP LH	1		\$485.00
8	REAR TAILGATE LAMP RH	1		\$485.00
9	REAR TAIL LAMP LH	1		\$643.00
10	REAR TAIL LAMP RH	1		\$643.00
11	REAR BUMPER	1		\$1,835.00
12	REAR BUMPER SIDE RETAINER LH	1		\$140.00
13	REAR BUMPER SIDE RETAINER RH	1		\$140.00
14	REAR BUMPER LOWER DIFFUSER	1		\$598.00
15	REAR BUMPER LOWER CHROME MOULDING	1		\$355.00
16	REAR BUMPER REINFORCEMENT	1		\$523.00
17	REAR BUMPER REFLECTOR LH	1		\$64.00
18	REAR BUMPER REFLECTOR RH	1		\$64.00
19	REAR BUMPER PARKING SENSOR	2	\$285.00	\$570.00
20	REAR BUMPER CENTER BRACKET	1		\$124.00
21	REAR BUMPER TOW COVER	1		\$86.00
22	FRONT BONNET	1		\$1,720.00
23	FRONT BONNET HINGE LH	1		\$95.00
24	FRONT BONNET HINGE RH	1		\$95.00
25	FRONT BONNET ACTUATOR LH	1		\$237.00
26	FRONT BONNET ACTUATOR RH	1		\$237.00
27	FRONT HEADLAMP LH	1		\$3,397.00
28	FRONT HEADLAMP RH	1		\$3,397.00
29	FRONT GRILLE BASE	1		\$1,007.00
30	FRONT UPPER GRILLE LH	1		\$140.00
31	FRONT UPPER GRILLE RH	1		\$140.00
32	FRONT LOWER GRILLE LH	1		\$140.00
33	FRONT LOWER GRILLE RH	1		\$140.00
34	FRONT GRILLE OUTER GARNISH	1		\$290.00
35	FRONT GRILLE CHROME MOULDING LH	1		\$68.00
36	FRONT GRILLE CHROME MOULDING RH	1		\$68.00
37	FRONT GRILLE LOGO EMBLEM	1		\$174.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 588047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 30/05/2023
Vehicle No: SNH156B
Model: MERCEDES BENZ A200 HATCHBACK
Chassis: W1K1770872N159493-2020
Reg.Year: 2022

Third Party Insurer: LONPAC
Third Party Veh No: YQ6759U
Date of Accident: 29/05/2023
Estimator: TING AN
Surveyor:

38	FRONT GRILLE LOGO BASE	1		\$165.00
39	FRONT RADAR SENSOR	1		\$1,320.00
40	FRONT RADAR SENSOR BRACKET	1		\$68.00
41	FRONT BUMPER	1		\$1,700.00
42	FRONT BUMPER "MERCEDES" EMBLEM	1		\$87.00
43	FRONT BUMPER SIDE RETAINER LH	1		\$35.00
44	FRONT BUMPER SIDE RETAINER RH	1		\$35.00
45	FRONT BUMPER INNER BRACKET LH	1		\$97.00
46	FRONT BUMPER INNER BRACKET RH	1		\$97.00
47	FRONT BUMPER INNER AIR GUIDE	1		\$550.00
48	FRONT BUMPER UPPER SUPPORT BRACKET	1		\$194.00
49	FRONT BUMPER REINFORCEMENT	1		\$497.00
50	FRONT BUMPER ABSORBER FOAM	1		\$152.00
51	FRONT BUMPER LOWER GRILLE	1		\$280.00
52	FRONT BUMPER LOWER CHROME MOULDING	1		\$373.00
53	FRONT SUPPORT PANEL	1		\$762.00
54	FRONT AIRCON CONDENSER	1		\$1,368.00
55	FRONT RADIATOR	1		\$1,252.00
56	FRONT FENDER LH	1		REPAIR
57	FRONT FENDER RH	1		REPAIR
SUB TOTAL				\$30,815.00
LESS 10%				-\$3,081.50
PARTS TOTAL				\$27,733.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		\$80.00
2	REAR BUMPER CLIPS	1		\$50.00
3	REAR END PANEL JOINT SEALANT	1		\$150.00
4	REAR END PANEL UPPER COVER CLIPS	1		\$40.00
5	FRONT GRILLE CLIPS	1		\$50.00
6	FRONT BUMPER CLIPS	1		\$50.00
7	FRONT RADIATOR COOLANT	1		\$80.00
S/N TOTAL				\$500.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 30/05/2023
Vehicle No: SNH156B
Model: MERCEDES BENZ A200 HATCHBACK
Chassis: W1K1770872N159493-2020
Reg.Year: 2022

Third Party Insurer: LONPAC
Third Party Veh No: YQ6759U
Date of Accident: 29/05/2023
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	\$800.00
LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.	\$800.00
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL, FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH & ETC.	\$1,600.00
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC.	\$150.00
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER PARKING SENSOR & ETC.	\$120.00
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$150.00
TO DIAGNOSIS FAULT CODE & PROGRAMMING.	\$500.00
TO REFILL AIRCON GAS & ETC.	\$120.00
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$150.00

LABOUR TOTAL	\$4,510.00
---------------------	-------------------

TING AN	TOTAL	\$32,743.50
----------------	--------------	--------------------

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

