

Date: 30/05/2023

Vehicle No: SNH156B

Model: MERCEDES BENZ A200 HATCHBACK

Chassis: W1K1770872N159493-2020

Reg.Year: 2022

Third Party Insurer: LONPAC

Third Party Veh No: YQ6759U

Date of Accident: 29/05/2023

Estimator: TING AN

Surveyor:

*Not Authorized*  
*U/Ry &*

*Missing After Pain* *8-10 days*

## ESTIMATE

| NO. | DESCRIPTION                       | QTY | UNIT S\$ | AMOUNT S\$           |
|-----|-----------------------------------|-----|----------|----------------------|
| 1   | REAR TAILGATE                     | 1   |          | <i>B</i> \$2,580.00  |
| 2   | REAR TAILGATE "A200" EMBLEM       | 1   |          | <i>Re</i> \$138.00   |
| 3   | REAR TAILGATE "MERCEDES" EMBLEM   | 1   |          | <i>Re</i> \$66.00    |
| 4   | REAR TAILGATE INNER LOCK          | 1   |          | <i>Re</i> \$328.00   |
| 5   | REAR TAILGATE INNER TRIM BOARD    | 1   |          | <i>Re</i> \$220.00   |
| 6   | REAR TAILGATE WEATHERSTRIP        | 1   |          | <i>Re</i> \$351.00   |
| 7   | REAR TAILGATE LAMP LH             | 1   |          | <i>CM</i> \$485.00   |
| 8   | REAR TAILGATE LAMP RH             | 1   |          | <i>CM</i> \$485.00   |
| 9   | REAR TAIL LAMP LH                 | 1   |          | \$643.00             |
| 10  | REAR TAIL LAMP RH                 | 1   |          | <i>Re</i> \$643.00   |
| 11  | REAR BUMPER                       | 1   |          | <i>Bu</i> \$1,835.00 |
| 12  | REAR BUMPER SIDE RETAINER LH      | 1   |          | <i>Diy</i> \$140.00  |
| 13  | REAR BUMPER SIDE RETAINER RH      | 1   |          | <i>Re</i> \$140.00   |
| 14  | REAR BUMPER LOWER DIFFUSER        | 1   |          | <i>Re</i> \$598.00   |
| 15  | REAR BUMPER LOWER CHROME MOULDING | 1   |          | <i>Diy</i> \$355.00  |
| 16  | REAR BUMPER REINFORCEMENT         | 1   |          | \$523.00             |
| 17  | REAR BUMPER REFLECTOR LH          | 1   |          | <i>Re</i> \$64.00    |
| 18  | REAR BUMPER REFLECTOR RH          | 1   |          | <i>CM</i> \$64.00    |
| 19  | REAR BUMPER PARKING SENSOR        | 2   | \$285.00 | \$570.00             |
| 20  | REAR BUMPER CENTER BRACKET        | 1   |          | \$124.00             |
| 21  | REAR BUMPER TOW COVER             | 1   |          | <i>Re</i> \$86.00    |
| 22  | FRONT BONNET                      | 1   |          | <i>Re</i> \$1,720.00 |
| 23  | FRONT BONNET HINGE LH             | 1   |          | \$95.00              |
| 24  | FRONT BONNET HINGE RH             | 1   |          | \$95.00              |
| 25  | FRONT BONNET ACTUATOR LH          | 1   |          | \$237.00             |
| 26  | FRONT BONNET ACTUATOR RH          | 1   |          | \$237.00             |
| 27  | FRONT HEADLAMP LH                 | 1   |          | \$3,397.00           |
| 28  | FRONT HEADLAMP RH                 | 1   |          | \$3,397.00           |
| 29  | FRONT GRILLE BASE                 | 1   |          | <i>CM</i> \$1,007.00 |
| 30  | FRONT UPPER GRILLE LH             | 1   |          | \$140.00             |
| 31  | FRONT UPPER GRILLE RH             | 1   |          | \$140.00             |
| 32  | FRONT LOWER GRILLE LH             | 1   |          | \$140.00             |
| 33  | FRONT LOWER GRILLE RH             | 1   |          | \$140.00             |
| 34  | FRONT GRILLE OUTER GARNISH        | 1   |          | <i>CM</i> \$290.00   |
| 35  | FRONT GRILLE CHROME MOULDING LH   | 1   |          | \$68.00              |
| 36  | FRONT GRILLE CHROME MOULDING RH   | 1   |          | \$68.00              |
| 37  | FRONT GRILLE LOGO EMBLEM          | 1   |          | <i>Re</i> \$174.00   |

### Head office

8 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1893

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 30/05/2023  
 Vehicle No: SNH156B  
 Model: MERCEDES BENZ A200 HATCHBACK  
 Chassis: W1K1770872N159493-2020  
 Reg.Year: 2022

Third Party Insurer: LONPAC  
 Third Party Veh No: YQ6759U  
 Date of Accident: 29/05/2023  
 Estimator: TING AN  
 Surveyor:

|    |                                    |   |               |             |
|----|------------------------------------|---|---------------|-------------|
| 38 | FRONT GRILLE LOGO BASE             | 1 | CM \$165.00   | ✓           |
| 39 | FRONT RADAR SENSOR                 | 1 | RM \$1,320.00 | ✓           |
| 40 | FRONT RADAR SENSOR BRACKET         | 1 | CM \$68.00    | ✓           |
| 41 | FRONT BUMPER                       | 1 | RM \$1,700.00 | ✓           |
| 42 | FRONT BUMPER "MERCEDES" EMBLEM     | 1 | RM \$87.00    | ✓           |
| 43 | FRONT BUMPER SIDE RETAINER LH      | 1 | Dis \$35.00   | ✓           |
| 44 | FRONT BUMPER SIDE RETAINER RH      | 1 | RM \$35.00    | X           |
| 45 | FRONT BUMPER INNER BRACKET LH      | 1 | \$97.00       | ?           |
| 46 | FRONT BUMPER INNER BRACKET RH      | 1 | \$97.00       | ?           |
| 47 | FRONT BUMPER INNER AIR GUIDE       | 1 | \$550.00      | ?           |
| 48 | FRONT BUMPER UPPER SUPPORT BRACKET | 1 | \$194.00      | ?           |
| 49 | FRONT BUMPER REINFORCEMENT         | 1 | \$497.00      | ?           |
| 50 | FRONT BUMPER ABSORBER FOAM         | 1 | \$152.00      | ?           |
| 51 | FRONT BUMPER LOWER GRILLE          | 1 | \$280.00      | ?           |
| 52 | FRONT BUMPER LOWER CHROME MOULDING | 1 | RM \$373.00   | X           |
| 53 | FRONT SUPPORT PANEL                | 1 | \$762.00      | ?           |
| 54 | FRONT AIRCON CONDENSER             | 1 | \$1,368.00    | ?           |
| 55 | FRONT RADIATOR                     | 1 | \$1,252.00    | ?           |
| 56 | FRONT FENDER LH                    | 1 | REPAIR        |             |
| 57 | FRONT FENDER RH                    | 1 | REPAIR        |             |
|    |                                    |   | SUB TOTAL     | \$30,815.00 |
|    |                                    |   | LESS 10%      | -\$3,081.50 |
|    |                                    |   | PARTS TOTAL   | \$27,733.50 |

| NO. | SPECIAL NETT                     | QTY | UNIT S\$  | AMOUNT S\$  |
|-----|----------------------------------|-----|-----------|-------------|
| 1   | REAR WINDSCREEN SEALANT          | 1   |           | RM \$80.00  |
| 2   | REAR BUMPER CLIPS                | 1   |           | RM \$50.00  |
| 3   | REAR END PANEL JOINT SEALANT     | 1   |           | RM \$150.00 |
| 4   | REAR END PANEL UPPER COVER CLIPS | 1   |           | \$40.00     |
| 5   | FRONT GRILLE CLIPS               | 1   |           | RM \$50.00  |
| 6   | FRONT BUMPER CLIPS               | 1   |           | RM \$50.00  |
| 7   | FRONT RADIATOR COOLANT           | 1   |           | \$80.00     |
|     |                                  |     | S/N TOTAL | \$500.00    |

Date: 30/05/2023  
Vehicle No: SNH156B  
Model: MERCEDES BENZ A200 HATCHBACK  
Chassis: W1K1770872N159493-2020  
Reg.Year: 2022

Third Party Insurer: LONPAC  
Third Party Veh No: YQ6759U  
Date of Accident: 29/05/2023  
Estimator: TING AN  
Surveyor:

## LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

500  
\$800.00

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

600  
\$800.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL, FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH & ETC.

1400  
\$1,600.00

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC.

\$150.00 120

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

\$120.00 60

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER PARKING SENSOR & ETC.

\$120.00 60

TO TUFF KOTE & UNDERSEAL MATERIALS.

~ \$150.00 x

TO DIAGNOSIS FAULT CODE & PROGRAMMING.

\$500.00 ?

TO REFILL AIRCON GAS & ETC.

\$120.00 ?

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$150.00 40

LABOUR TOTAL \$4,510.00

TOTAL \$32,743.50

TING AN

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

### Head office

8 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

