



PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers

Blk 779 Yishun Avenue 2

#01-1545 Singapore 760779

Tel: 6293 4822 Fax: 6296 3283

E-mail: admin@priorityservices.sg

Messrs. Sompoo Insurance Pte Ltd
50 Singapore Land Tower
#03-03 Raffles Place
Singapore 048623

Bill No : DN/00615/21

Date : 22/4/2021

Dr.

To

Survey Fee (S\$) : 200.00

Photographs (S\$) :

Transport (S\$) :

Resurvey (S\$) :

Miscellaneous (S\$) :

Services rendered including photographs and transport charges

(S\$) : 200.00

Our Reference : TP-0095/04/21

Insured : GBC 3401 S

Date Of Accident : 27/12/2020

Policy / Cert. No. : Paper Survey

Your Claim No : CMTD2100045/THE

Vehicle : Mazda 5 (A) - SKV 5713 Y

Dollars : Two Hundred ONLY

For PRIORITY SERVICES

E & O.E.



PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers
Blk 779 #01-1545 Yishun Ave 2 Singapore 760779
Tel: 62934822 Fax: 62963283
E-mail: admin@priorityservices.sg

Date: 22 April 2021

Your Ref: CMTD2100045/THE

Our Ref: TP-0095/04/21

Motor Claims Department
M/s. Sampo Insurance Pte. Ltd.
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623

Attention: Ms. Thelma Choo

Madam,

Inspection of 2015 Mazda 5 (A)
Registration No.: SKV 5713 Y
Odometer Reading: 76584 km
Chassis No.: JM6CW1071G0122280

We refer to your instructions to us to conduct a paper survey of the above vehicle. A pre-repair survey was conducted on 11-01-2021, followed by resurvey after repairs on 14-01-2021. The repairer did not arrange for another survey after parts have been dismantled.

The following documents were received: -

- 1) Copy of survey report by M/s. KTO Automobile Assessors
- 2) 20 copies of photos depicting damages sustained by SKV 5713 Y
- 3) Accident reports by drivers of SKV 5713 Y and GBC 3401 S

The vehicle sustained rear left damages during an accident on 27-12-2020.

Repair cost submitted was \$4,500.00 lump-sum.

We append below our findings: -

<u>Replacement of Parts</u>		<u>Revised Amount</u>	<u>Our Recommendation</u>
1pc.	Rear bumper – not replaced	\$ 961.00	\$ -
1pc.	Rear bumper side retainer LH – no evidence of damage	62.50	-
1pc.	Rear bumper bracket LH – no evidence of damage	22.50	-
1pc.	Rear tail gate – repaired	1,637.00	-
1pc.	Rear tail gate lamp LH	-	419.00
1pc.	Rear tail lamp LH	-	690.60

1pc.	Rear tail gate MAZDA logo	\$ -	\$ 53.70
1pc.	Rear tail gate MAZDA 5 emblem	-	53.00
1pc.	Rear tail gate SKYACTIV emblem	-	53.90
		=====	=====
		\$ 2,683.00	\$ 1,270.20
	Less 20%	536.60	254.04
		=====	=====
		\$ 2,146.40	\$ 1,016.16

Special Nett Items:-

1set	Rear bumper clips – not necessary	\$ 34.00	\$ -
1pc.	Rear tail gate lamp LH – refer to List item	419.00	-
1pc.	Rear tail lamp LH – refer to List item	690.60	-
1pc.	Rear windscreen glass moulding – not necessary	130.60	-
1pc.	Rear windscreen glass spacer – not necessary	29.00	-
1pc.	Rear tail gate MAZDA logo – refer to List item	53.70	-
1pc.	Rear tail gate MAZDA 5 emblem – refer to List item	53.00	-
1pc.	Rear tail gate SKYACTIV emblem – refer to List item	53.90	-
1pc.	Rear bumper reverse sensor – no evidence of damage	193.90	-
		=====	=====
	Total For Parts:-	\$ 3,804.10	\$ 1,016.16
		=====	=====

Labour Charges:-

Spray painting on above new and repaired parts including supply of paint materials.	\$ 700.00	\$ 500.00
Remove damaged parts, straighten, knock out dents, panel beating, remove, reinstall necessary fittings to facilitate repairs, adjust, replace and realign all relevant parts.	750.00	400.00
To cavity preservation on all affected areas.	60.00	30.00
To transfer rear tail gate mechanism and component. – not necessary	50.00	-
To remove and reinstall rear windscreen glass to assist repair. – not necessary	120.00	-
Check wiring, lighting, reconnection socket, wiper motor and central locking system for proper function.	30.00	30.00
To reinstall rear bumper sensor and check for proper function. – not necessary	80.00	-
To supply rear windscreen glass sealant. – not necessary	40.00	-

Total:-

\$ 5,634.10

\$ 1,976.16

Lump-sum repairs:

\$ 4,500.00

\$ 1,550.00

Estimated period of repairs: 3 working days

Pre-accident Market Value : About \$ 52,000.00

PARF/COE rebate : \$ 41,662.00

Vehicle within economical limit to repair.

We leave the decision of settlement to you.

Assuring you of our best services always

Yours faithfully

PRIORITY SERVICES



JIMMY S. T. LEE AMSOE, AMIRTE, MSAAA
Motor Appraiser

Surveyed by:



LAWRENCE NG, MSAAA
Motor Appraiser