* PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS

 WORKSHOP
 : UBI ROAD 1

 CONTACT NO
 : 6366 2323

 FAX NO
 : 6841 1183

REFERENCE : PA/OD/0507/2023/EQ

DATE : 29-May-23 **WIP** : 22488

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/5/2023.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR QIU MINGJIE

ADDRESS : 28 SUMANG WALK

#12-13

SINGAPORE 828619

TELEPHONE : HP +65 98513379 **TYPE OF CLAIM** : OWN DAMAGE CLAIM

POLICY NO : 7230021840

VEHICLE NO : SNJ 8529 X

MODEL CODE : AUDI A5 SPORTBACK 2.0 TFSI

 MODEL YEAR
 : 28/2/2023

 ENGINE NO
 : DEM 038776

CHASSIS NO : WAUZZZF5XPA004319

MILEAGE : DATE IN : -

ESTIMATED BY : JOHNNY BOO / ALLAN WU

ACCIDENT DATE : 26-May-23

PLACE OF ACCIDENT : 28 SUMANG WALK, SINGAPORE 828623





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNJ 8529 X

TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES. TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. TO RESPRAY RHS FRONT FENDER AND RHS FRONT DOOR. 5 TO CARRY OUT DIAGNOSTIC CHECK. S/N \$ 192.00 TOTAL LABOUR CHARGES : \$ 6,772.00	S/N	NATURE OF JOBS		CHARGES	SURVEYOR'S RECOMMENDATIONS	
2 LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES. TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. 4 TO RESPRAY RHS FRONT FENDER AND RHS FRONT DOOR. \$ 2,500.00 // \$ 3 TO CARRY OUT DIAGNOSTIC CHECK.	_1_	FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING		\$ 480.00	χ.	
RENEW RHS FRONT FENDER AND RHS FRONT DOOR. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. 4 TO RESPRAY RHS FRONT FENDER AND RHS FRONT DOOR. 5 TO CARRY OUT DIAGNOSTIC CHECK. 5 3,200.00 / 5 3 3 3,200.00 / 5 3 3 3,200.00 / 5 3 3 3,200.00 / 5 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	2	LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT	S/N	\$ 400.00	280	
5 TO CARRY OUT DIAGNOSTIC CHECK. 5/N \$ 192.00	3	RENEW RHS FRONT FENDER AND RHS FRONT DOOR. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS.		\$ 3,200.00	1500	
	4	TO RESPRAY RHS FRONT FENDER AND RHS FRONT DOOR.		\$ 2,500.00	1100	
TOTAL LABOUR CHARGES : \$ 6,772.00	5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	/	
		TOTAL LABOUR CHARGES	:	\$ 6,772.00		





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNJ 8529 X

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER - RH Dented	1	\$ 1,258.00	
2	FRONT FENDER ATTACHMENT PARTS / ~ ~	1	\$ 59.00	1.
3	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 88.00	+
4	FRONT FENDER BRACKET - RH	1	\$ 44.00	4
5	FRONT FENDER RIVET	6	\$ 24.00	
6	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 39.00)
7	FRONT FENDER CHROME TRIM - RH	1	\$ 181.00	
8	FRONT DOOR - RH Devted	1	\$ 4,210.00	
9	FRONT DOOR OUTER SEAL M	1	\$ 261.00	1
10	BONDING AGENT	1	\$ 51.00	2
11	CLEANING SOLUTION	1	\$ 80.00	7
12	APPLICATOR	1	\$ 9.00	7
13	FRONT DOOR CATCH 7	1	\$ 141.00	?
14	FRONT DOOR CHROME TRIM - RH	1	\$ 181.00	
15	FRONT TYRE PRESSURE DATA PLATE	1	\$ 43.00	~
16	SUNDRIES ?		\$ 500.00	7
	TOTAL SPARE PARTS	:	\$ 7,169.00	
	TOTAL LABOUR CHARGES	:	\$ 6,772.00	
	GRAND TOTAL	:	\$ 13,941.00	, i

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED SPARE PARTS ARE SPECIAL NETT.





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE EXCESS COST

LIABILITY

REMARKS

Adrin L 30/05/23.

: Atl Authorsed, 04 Dup

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY, PREMIUM AUTOMOBILES PTE LTD

> LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ALLAN WU

CLAIMS CONSULTANT

JOHNNY BOO **BODY REPAIR MANAGER**