

Date: 30/5/2023
Vehicle No: SNJ7991A
Model: NISSAN SERENA 1.2L HIGHWAY STAR
Chassis: JN1EBAC27Z0001620
Reg.Year: 2023

Third Party Insurer: AIG
Third Party Veh No: SMR9207M
Date of Accident: 12/3/2023
Estimator: SIMON KOH
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER COVER	1	\$ 660.00	\$ 660.00
2	FRONT BUMPER SIDE BRACKET RH	1	\$ 46.00	\$ 46.00
SUB TOTAL				\$ 706.00
LESS 10%				-\$ 70.60
PARTS TOTAL				\$ 635.40

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1	\$ 50.00	\$ 50.00
S/N TOTAL				\$ 50.00

LABOUR CHARGES:

LABOUR TO REMOVE, REPLACE/REPAIR, REALIGN AND REFIX THE LISTED ACCIDENT
AFFECTED DAMAGED PARTS \$ 400.00

LABOUR TO PUTTY, RESPRAY AND POLISH FRONT BUMPER, FRONT RH FENDER AND
OTHER ACCIDENT AFFECTED AREA \$ 400.00

LABOUR TOTAL \$ 800.00

Simon **TOTAL \$ 1,485.40**

*Not withair
Painting After Pain
1 day*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

