

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT  
#01-49 SINGAPORE 415875  
Tel: +65 64524457  
Fax: +65 64524584

Vehicle number: YP7529R

**Make & Model:** Mitsubishi Canter

Chassis number: FEB21EA21601

No.	Description of spare parts	Qty	Amount S\$
1	RH taillamp assy	1	\$ <i>Cur</i> 360.00
2	LH taillamp assy	1	\$ <i>X nn</i> 360.00
3	Rear number plate lamp	1	\$ <i>X nn</i> 93.00
4	Air cleaner upper duct	1	\$ <i>de</i> 212.00
5	Air cleaner duct flex hose	1	\$ <i>x nn</i> 132.00
6	Air cleaner box	1	\$ <i>x nn</i> 854.00
7	Radiator spare tank	1	\$ <i>x nn</i> 163.00

	\$	2,174.00
Parts less 25%	\$	543.50
Total:	\$	1,630.50

No.	Special Nett Items	Qty	Amount S\$
1	Wooden tailgate	1	\$ <i>org</i> 2,200.00
2	Wooden tailgate frame	1	\$ <i>bt</i> 1,850.00
2	Wooden tailgate lower member	1	\$ <i>Cua</i> 1,600.00
2	Wooden tailgate lower member fasteners	1set	\$ <i>nel</i> 100 150.00
3	Wooden tailgate "60km/h" sticker	1	\$ <i>nel</i> 28.00
4	Wooden tailgate "23pax" sticker	1	\$ <i>nel</i> 28.00
5	Wooden tailgate RH side hinge	1	\$ <i>bt</i> 340.00
6	Wooden tailgate RH centre hinge	1	\$ <i>x nn</i> 340.00
7	Wooden tailgate LH centre hinge	1	\$ <i>x nn</i> 340.00
8	Wooden tailgate LH side hinge	1	\$ <i>x nn</i> 340.00
9	Rear number plate	1	\$ <i>x nn</i> 50.00
10	Wooden step	1	\$ <i>x nn</i> 580.00
11	Rear RH chassis wooden member	1	\$ <i>x nn</i> 1,600.00
12	Rear RH chassis wooden member fasteners	1set	\$ <i>x nn</i> 220.00
13	Rear LH chassis wooden member	1	\$ <i>x nn</i> 1,600.00
14	Rear LH chassis wooden member fasteners	1set	\$ <i>x nn</i> 220.00
15	Rear platform wooden members	3	\$ <i>org</i> 440.00
16	Rear step bracket	1	\$ <i>x nn</i> 1,400.00
17	Wooden front gate	1	\$ <i>x nn</i> 2,200.00
18	Wooden front gate frame	1	\$ <i>x nn</i> 1,850.00
19	Wooden front gate guard	1	\$ <i>x nn</i> 1,850.00
20	RH side wooden gate	1	\$ <i>org</i> 2,800.00
21	RH side wooden gate frame	1	\$ <i>x nn</i> 2,200.00

3375

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 900 3,200.00
2	Spray painting on affected areas and panels	\$ 700 1,800.00
3	Check wiring and lighting system on affected areas	\$ 30 100.00
4	Apply rust coating chemical on affected areas and panels	\$ X 180.00
5	Lift up wooden platform to assist repair and replace parts	\$ 200 1,200.00
6	Lift up rear canopy assy to assist repair	\$ 200 750.00

Agreed Amount: \_\_\_\_\_ (Part by Part / Lump sum)  
Working days: \_\_\_\_\_

2130 Total: \$ 4,030.00

5859

Spare Parts: \$ 1,630.50

Special Nett: \$ 24,226.00

L/S - 4687.20  
= 4700

Labour: \$ 4,030.00

Total Amount: \$ 29,886.50

Tanpin 97495749

WP' 31/5/23 & 220

c/b Resurvey after repair

Tanpin C/Manito.com

- To check consistency of accident  
- To check part prices

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: