

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SMH5771D

Make & Model: Toyota Vios

Chassis number: MR053HY9305103304

No.	Description of spare parts	Qty	Amount S\$
		1	\$ <i>bf</i> 681.40
1	Bootlid	1	\$ <i>new</i> 49.30
2	Bootlid "Vios" emblem	1	\$ <i>new</i> 45.70
3	Bootlid centre emblem	1	\$ <i>new</i> 28.30
4	Bootlid "J" emblem	1	\$ <i>x</i> 246.10
5	Bootlid number plate outer moulding	1set	\$ <i>x</i> 40.00
6	Bootlid number plate outer moulding clips	1	\$ <i>x</i> 96.80
7	Bootlid RH number plate lamp	1	\$ <i>x</i> 96.80
8	Bootlid LH number plate lamp	1	\$ <i>x</i> 97.80
9	Bootlid RH hinge	1	\$ <i>x</i> 97.80
10	Bootlid LH hinge	1	\$ <i>bf</i> 211.70
11	Bootlid lock	1	\$ <i>x</i> 48.10
12	Bootlid lock catch	1	\$ <i>cut</i> 271.80
13	Bootlid weatherstrip	1	\$ <i>de</i> 561.80
14	Rear bumper	1set	\$ <i>3over</i> 80.00
15	Rear bumper clips	1	\$ <i>new</i> 187.75
16	Rear bumper RH reflector	1	\$ <i>x</i> 187.75
17	Rear bumper LH reflector	1	\$ <i>x</i> 171.45
18	Rear bumper RH side holder bracket	1	\$ <i>x</i> 171.45
19	Rear bumper LH side holder bracket	1	\$ <i>x</i> 98.70
20	Rear bumper RH side splash shield	1	\$ <i>x</i> 98.70
21	Rear bumper LH side splash shield	1	\$ <i>hb</i> 791.45
22	End panel	1	\$ <i>de</i> 193.00
23	End panel top garnish	1set	\$ <i>2over</i> 50.00
24	End panel top garnish clips	1	\$ <i>x</i> 89.50
25	End panel RH side bracket	1	\$ <i>x</i> 89.50
26	End panel LH side bracket	1	\$ <i>cur</i> 342.50
27	RH tailamp assy	1	\$ <i>x</i> 43.70
28	RH tailamp sponge gasket	1	\$ <i>x</i> 184.70
29	RH taillamp panel	1	\$ <i>cur</i> 342.50
30	LH tailamp assy	1	\$ <i>x</i> 43.70
31	LH tailamp sponge gasket	1	\$ <i>x</i> 184.70
32	LH taillamp panel	1	\$ <i>xn</i> 387.75
33	Rear RH fender inner trim	1set	\$ <i>x</i> 60.00
34	Rear RH fender inner trim clips	1	\$ <i>x</i> 387.75
35	Rear LH fender inner trim		

36	Rear LH fender inner trim clips	1set	\$ X	60.00
37	Exhaust silencer	1	\$ x	781.10
38	Exhaust silencer gasket	1	\$ x	63.70
39	Exhaust silencer rubber mountings	1	\$ x	109.55
40	Spare tyre panel tool sponge centre tray	1	\$ X	285.30
41	Spare tyre panel tool sponge RH tray	1	\$ <i>ans</i>	285.40
42	Spare tyre panel tool sponge LH tray	1	\$ <i>ans</i>	285.40
43	Spare tyre panel top board cover	1	\$ X	375.10
44	Spare tyre lock screw	1	\$ x	45.10

\$ 9,050.60
 Parts less 25% \$ 2,262.65
 Total: \$ 6,787.95

No.	Special Nett Items	Qty	Amount S\$
1	Rear number plate	1	\$ x 70.00
2	Rear bumper reverse sensor	1set	\$ <i>200nw</i> 350.00
3	End panel joint sealant	1	\$ <i>40nw</i> 80.00
Total:			\$ 500.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ <i>600</i> 1,400.00
2	Spray painting on affected areas and panels	\$ <i>600</i> 1,200.00
3	Check wiring and lighting system on affected areas	\$ <i>30</i> 60.00
4	Apply rust coating chemical on affected areas and panels	\$ <i>30</i> 80.00
5	Remove and replace rear bumper reverse sensors to assist repair	\$ <i>30</i> 100.00
6	Remove and replace rear inner trims, garnish and board to assist repair	\$ <i>60</i> 320.00
7	Remove and replace exhaust silencer and gasket to assist repair	\$ <i>X</i> 120.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Total: \$ 1,880.00

Spare Parts: \$ 6,787.95

Special Nett: \$ 500.00

Labour: \$ 1,880.00

Total Amount: \$ 9,167.95

Tanpin 97495741

WP - 31/5/23 @ 2pm

1/5 Resurvey after repair

Tanpin @ Kuantan W.M.

5 days

- To check consistency of accident
- To check part prices

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date: