

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ivy Yong

Date: 01 Jun 2023

Preliminary Advice

Vehicle No	: GBJ4634T	Accident Date	: 27/05/2023
Make	: TOYOTA HIACE	Policy No.	: DMCG23004473
Assignment Date	: 31/05/2023	Excess	: S\$500.00
Date of Inspection	: 31/05/2023	Est. Duration of Repair	: 14 days
Inspection At	: KAN FOOK SING MOTOR WORKSHOP		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,467.30
Revised Amount	:S\$	6,006.40
Check Items (Estimated)	:S\$	13,879.40
Total	:S\$	19,885.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	14,300.00
Salvage Value	:S\$	
Margin for Repair	:S\$	55,700.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Lump Sum Repair
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour costs.